

## **Abel, Albert**

---

**From:** Abel, Albert  
**Sent:** Wednesday, July 31, 2013 2:04 PM  
**To:** Zigan, Curtis  
**Cc:** Atkinson, Mark; Thompson, Ty  
**Subject:** RE: GUE 70 12.75L

Curtis,

I inspected the bridge. There is only minor damage that was caused by the fire and it does not warrant repairs. The photos have been uploaded to the Y drive file for the bridge named "2013 Inspection"

Albert

-----Original Message-----

From: Zigan, Curtis  
Sent: Wednesday, July 31, 2013 7:25 AM  
To: Abel, Albert  
Cc: Atkinson, Mark; Thompson, Ty  
Subject: RE: GUE 70 12.75L

Albert,

Will you look at this bridge? Write a work order to repair the parapet, if it's a safety concern. The bridge is rated as fellows: Railing - 2, Floor - 2, Wearing surface - 2, Paint - 6, and GA - 6A. The bridge was resurfaced last year, so the wearing surface may go to a 1 this year. The bridges are programmed for deck replacements in FY19, PID#-93281. The may move plus or minus a year depending on condition.

Thanks  
Curtis

-----Original Message-----

From: Atkinson, Mark  
Sent: Tuesday, July 30, 2013 7:10 AM  
To: Zigan, Curtis  
Subject: GUE 70 12.75L

The above referenced structure had a car fire on the structure per our conversation yesterday. I do not see any major issues caused by the fire, however as you can see, the parapets on this structure are in poor condition.