The Great Lakes Construction Co.

TRANSMITTAL No. 164

10737 Medallion Drive Cincinnati, Ohio 45241

PROJECT: ODOT 150085 HAM 71-1.34 **DATE:** June 15, 2017

TO: ODOT District 8 REF: Damper Door System Maintenance

505 South SR 741 Requirements for Actuators and

Lebanon, OH 45036 Chains

ATTN: Marvin Lennon

| WE ARE SENDING | | SUE | SUBMITTED FOR: | | ACTION TAKEN: | |
|----------------|-------------------------------|-----|--------------------|---|-------------------------|--|
| | Shop Drawings | | Approval | | Approved as Submitted | |
| | Letter | Х | Your Use | | Approved as Needed | |
| | Prints | | As Requested | | Returned after Loan | |
| | Change Order | | Review and Comment | | Resubmit | |
| | Plans | | | Х | Submit | |
| | Samples | SEN | NT VIA: | | Returned | |
| | Specifications | Х | Attached | | Returned for Correction | |
| Χ | Other: Additional Information | | Separate Cover: | | Due Date: | |

| <u>SUBMITTAL</u> | COPIES | <u>DATE</u> | DESCRIPTION | |
|------------------|---------------|--------------|---|--|
| Damper Door | | | | |
| System | 1 46 | C /4 F /2017 | Damper Door System Maintenance Requirements | |
| Maintenance | 1pdf | 6/15/2017 | for Actuators and Chains | |
| Requirements | | | | |

REMARKS: This Damper Door System Maintenance Requirements for Actuators and Chains submittal

provides additional information for maintenance that is not required per plans.

Signed:

Ryan W. Jones, P.E.



5271 BROTHERTON COURT · CINCINNATI, OHIO 45227 · PHONE: 513-561-5522 · FAX: 513-561-0166 · WWW.AIRECON.COM · INQUIRIES@AIRECON.COM

February 28, 2017

Debra-Kuempel 3976 Southern Avenue Cincinnati, Ohio 45227

Attention: Mr. Scott Meadows

Reference: Project: ODOT 1-71 Lytel Tunnel

Ham-71-01.34

Airecon Shop Order #P-5856 Operation & Maintenance Manuals

Dear Scott:

Please find attached the Rotork Actuator O & M Manual.

The following lubrication instructions apply to the bearings and chains.

<u>Bearings</u>

Dodge recommends using a lithium or lithium complex grease for bearing lubrication. Since the bearings are rotating at slow speeds, they only need to be relubricated every couple of months. However, since these are only in operation periodically, they need to be filled to 100%.

Chains

The chains are to be lubricated with SAE 10W 40 oil every couple of months.

If you have any questions regarding this matter, please do not hesitate to contact us.

Sincerely,

Airecon Manufacturing Corp

Paul J. Bockrath Sales Engineer

Pb-dk-sm-p5856-manuals