

CRS:	COL-Little Beaver Creek Greenway	PID:	124275	Date:	11/20/25
------	----------------------------------	------	--------	-------	----------

ENVIRONMENTAL SOS

Task	Task#	Required	Preparer	Comments
CE Level: C2	3.5.A	X	Consultant	
Purpose and Need Statement	1.3.G			
Cultural Resource SRF	2.2.B	X	Consultant	
Phase I Cultural Archaeological	3.1.A			
Phase I Cultural History Arch	2.2.I			
Phase II Cultural History Arch	3.1.B			
Section 4(f) Determination/Coord	2.2.F & 3.1.C	X	Consultant	
Recreational Boating Review Form	NA			
Ecological Survey Level: 1	2.2.C	X	Consultant	
Mussel Survey	3.1.Q	X	Consultant	If-authorized
Section 9/Section 10 Coordination	3.1.M.C			
Permit Determination Request	3.1.M.A	X	Consultant	
Section 404 PCN	3.1.M.B	X	Consultant	If-authorized
404 Individual Permit	3.1.M.D			
OEPA Director's Authorization App	3.1.M.H			
401 Water Quality Application	3.1.M.C			
Flood Plain Coordination	2.3.H.A	X	Consultant	Zone A
Scenic River Coordination	NA			
Public Involvement	2.2.A & 2.6.A	X	D11 & LPA & Consult	See comments
FCIR Form	3.1.E			
RMR Screening	2.2.D	X	Consultant	
RMR Assessment	3.1.D			
RMR Investigation	3.1.O			
Noise Analysis	2.2.G & 2.2.H			
Air Quality Analyses	3.1.P			
Asbestos Inspection	NA	X	Consultant	See Comments

CRS:	COL-Little Beaver Creek Greenway	PID:	124275	Date:	11/20/25
------	----------------------------------	------	--------	-------	----------

ENVIRONMENTAL SOS

Additional Comments:
Public Involvement PONL by consultant for field work access only Web release on ODOT and LPA websites for public comment Asbestos Inspections Any structures with a span of 10’ or greater being replaced will require an asbestos inspection.

