



Cuy-6-1456 SFN 1800930 Corbel Spalls Remove immediately



Span 6 South side  
Corbel need to be removed immediately