



CUY-480-1216
SFN 1812971

P1: BEARING PAD #1 AT START HAS SHIFTED AS MUCH AS 1.25"



P2: NOTE THE SHIFT IN THE ELASTOMERIC BEARING. START-RIGHT BEARING.



P3: AS MUCH AS 2" ROTATION OF THE BRIDGE DECK.

CUY-480-1216
SFN 1812971



P4: ARROW POINTS TO SHEAR CRACK IN CAP OF PIER #1.
LOOKING AT FINISH ABUT.



P5: CLOSE UP OF P4.



P6: SAME AS P5, OTHER SIDE OF PIER.