III.A. Centerline Cuts Checklist

C D C, CCI 922 0 00 (Ctore 1)	DID: 77266	Davious P Mott/E Too	Data: 11 16 07
C-R-S: SCI-823-0.00 (Stage 1)	PID: 77366	Reviewer: B. Mott/E. Tse	Date: 11-16-07

If you do not have a centerline cut on the project, you do not have to fill out this checklist.

Soi	l Cı	uts			
Y	N	X	1	Does drilling provide continuous stratigraphic sections for the range of elevations that represent proposed cut slope areas?	
<u>Y</u>	N	Χ	2	Do the cut slopes have a minimum stability F.S. of 1.30 and are not steeper than 2:1?	
				Check stability calculation method used:	
				STABL or equivalent software	
				☐ hand calculations	
<u>Y</u>	N	X	3	If there is a "red bed" or other historically unstable soil or rock layer through the cut slopes, was this layer considered as a possible failure zone?	
Y	N	<u>X</u>	4	Have erosion protection measures been addressed for backslopes, side slopes, and ditches (including riprap recommendations or special slope treatments)?	
Υ	N	<u>X</u>	5	Have issues related to any special usage of excavated soils been addressed?	
			6	If the cut is not completely above the water table,	
Υ	N	<u>X</u>		a Did the design consider the construction or long term ramifications of cutting below the water table?	
Υ	N	<u>X</u>		b Did the design consider additional drainage in the cut slope (springs / seeps) and roadway base?	
Ro	Rock Slopes				
				For rockfall and additional design considerations, see the "Rockfall Corrections Checklist."	
Y	N	X	7	Has the subsurface exploration adequately characterized the rock in accordance with the Geotechnical Bulletin 3: Rock Cut Slope and Catchment Design (GB 3)?	
<u>Y</u>	N	X	8	Have the slope angles, benching scheme, rockfall catchment design, and drainage controls been determined as prescribed in GB 3?	
<u>Y</u>	N	X	9	In accordance with GB 3, are the rock cut slopes, benches, and catchment areas indicated on all appropriate cross-sections?	

III.A. Centerline Cuts Checklist

Y N X 10 In accordance with GB 3, has the rockfall catchment software analysis output and the cost analysis comparing catchment configurations been provided?

Notes:

Stage 1: