

This presentation will provide an overview of the subject project that will be placed on the upcoming programmatic selection for consultant design services.

COL-518-0.99 PID 115053

 Proj. Description: Replace bridge carrying State Route 518 over Willard Run.





2 | Proj. COL-518-0.99 PID 115053



The project will replace bridge COL-518-0.99 (SFN 1505408) carrying SR 518 over Willard Run.

AVAILABLE PROJECT INFORMATION

- Some project information is available at the following FTP site:
 - https://ftp.dot.state.oh.us/pub/Districts/D11/115053
 - Internet Explorer recommended for the ftp site
 - The PIP will be released through SAFE on the programmatic scheduled date
 - D11 does not release the PIP early
 - All information on the FTP site is subject to change, please review the information in SAFE to create your LOI




3 | Proj. COL-518-0.99 PID 115053





Additional project information is available on the District 11 ftp site, at the link shown on your screen. The Project Initiation Package document, along with a more complete and detailed scope of work will be released through The ODOT Scope and Fee System (or SAFE) at the request for LOIs. All information on the FTP site is subject to change. Ensure you review the ftp site and the information in SAFE before completing your LOI for this project.



Here is an image showing the anticipated project limits from ODOT's TIMS application. The project will follow the existing horizontal and vertical alignments as much as practical.

PROJECT SCOPE

- The major items of work include:
 - Replace Three-Span Slab Bridge with new structure.
 - Soil Borings Required
 - Detour SR 518 for Maintenance of Traffic during school recess.



5 | Proj. COL-518-0.99 PID 115053






The major scope items are listed here. An updated and more complete list will be released in SAFE at the beginning of the LOI process.

CONSULTANT PREQUALIFICATIONS

- Level 1 BRG INSP
- Level 2 BRG DSGN
- Non-Complex ROAD
- Various ENV
- Various GEO





6 | Proj. COL-518-0.99 PID 115053






The following slides will show you some of the scoping field visit photos, as well as structure inspection report photos, to illustrate how the District arrived at the current scope of work. More photos are available on the ftp site shown earlier.









THANK YOU

- Additional photos are available on the FTP Site.
- Thank you for watching this video presentation for Proj. COL-518-0.99 PID 115053.
- District 11 appreciates your interest in partnering with us for a successful project.



12 | Proj. COL-518-0.99 PID 115053



Thank you for watching this video. Visit the ftp site for more photos and information. Please remember that changes to this information and the detailed scope of work are possible. Review the information in SAFE prior to submitting your LOI.

