
RE: PID 116626 - HAM-275-5.25 Review Plans - Utility Coordination

From Ronan, James <JARONAN@eprod.com>

Date Wed 2025-12-10 11:49 AM

To Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Cc 10445264_Terracon-TO A-HAM-275 <10445264_Terracon-TOA-HAM-275@hdrinc.com>

CAUTION: [EXTERNAL] This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hunter,

Thank you for your patience, and I apologize for the delayed response. I appreciate your understanding. I have reviewed the area in question, and I can confirm that there are no conflicting Enterprise utilities present that would impact the landslide repair project. From our perspective, you are clear to proceed with the planned work.

Please let me know if you need any additional information or documentation to move forward. I'm happy to assist if anything further is required.

Thanks,

Jim Ronan
Pipeline Technician
Todhunter Area
(513)465-9890



From: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Sent: Wednesday, December 10, 2025 9:41 AM

To: Ronan, James <JARONAN@eprod.com>

Cc: 10445264_Terracon-TO A-HAM-275 <10445264_Terracon-TOA-HAM-275@hdrinc.com>

Subject: [EXTERNAL] Re: PID 116626 - HAM-275-5.25 Review Plans - Utility Coordination

[Use caution with links/attachments]

Good morning Jim,

Following up to see if you have had a chance to review the project area and confirm there are no conflicting Enterprise utilities present for the landslide repair project?

Thanks,

Hunter Durbin, PE

D 614.948.1562

hdrinc.com/follow-us

From: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Sent: Wednesday, November 26, 2025 9:24 AM

To: jaronan <JARONAN@eprod.com>

Subject: Re: PID 116626 - HAM-275-5.25 Review Plans - Utility Coordination

Good morning Jim,

Here is a link to the project area in Google Maps: <https://maps.app.goo.gl/93RhMzejhXnRk5vTA>

If you turn on the aerial imagery the landslide can be seen where the trees are missing from the tree line on the northside of I-275.

Let me know if you need anymore information.

Thanks,

Hunter Durbin, PE

D 614.948.1562

hdrinc.com/follow-us

From: Ronan, James <JARONAN@eprod.com>

Sent: Tuesday, November 25, 2025 12:23 PM

To: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Subject: RE: PID 116626 - HAM-275-5.25 Review Plans - Utility Coordination

CAUTION: [EXTERNAL] This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Can you please provide GPS coordinates of the work area?

Thanks!

Jim Ronan
Pipeline Technician
Enterprise Products
(513) 465-9890

From: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Sent: Friday, November 21, 2025 4:13 PM

Cc: Braun, Lucas <Lucas.Braun@dot.ohio.gov>; Durham, Paul <Paul.Durham@hdrinc.com>

Subject: [EXTERNAL] PID 116626 - HAM-275-5.25 Review Plans - Utility Coordination

[Use caution with links/attachments]

Good afternoon,

At the link below, you will find plans as they were transmitted to the Ohio Department of Transportation, District 8 for the Stage 2 Review of the HAM-275-5.25 Landslide Repair project. The project is located approximately 5 miles east of the Ohio border along I-275 and involves the construction of a 150-foot drilled shaft retaining wall along the exterior southbound shoulder of I-275 and associated drainage and pavement repair work. There are no known underground utilities within the construction limits of the project.

Please review and confirm that your existing facilities are not located within the project area and will not be impacted. If your existing facilities are present within the project area please include line size, depth/vertical clearances and any other pertinent information necessary for HDR to determine if relocation will be necessary or if minor design changes can be accommodated to avoid conflict.

Please return any comments or information on your facilities to us by Friday, December 19th. If you have any questions, please let me know.



[PID 116663 - HAM-275-5.25 - Stage 2 Plans.pdf](#)

Thank you,

Hunter Durbin, PE

Highway Engineer

HDR

8890 Lyra Drive, Suite 100

Columbus, OH 43240

D 614.948.1562

Hunter.Durbin@hdrinc.com

hdrinc.com/follow-us

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.