







INSERT B


594.35 EB	594.75 WB	596.95 EB	598.25 WB	598.95 EB	598.95 WB	599.35 EB	599.35 WB
594.35 EB	594.75 WB	596.95 EB	598.25 WB	598.95 EB	598.95 WB	599.35 EB	599.35 WB

Hub Top Bank
N&C 5' Elm
N&C 2' Box Elder
P.K. (Old) Dead Honey Locust
N&C 5' Cedar
P.K. 4' Elm
P.K. 4' Hickory
P.K. 4' Elm
P.K. 4' Hickory

P.O.T. 437+26.15
S.T. 439+83.37
P.O.T. 440+60.98

DEVELOPED CHECKED
1/22/77 R.J.D. 10-8-72 A.L.Y.

Excavation 45,396 CY
Embankment 10,390 CY
Seeding & Mulching 46,021 SY



I-275 STA. 431+00 TO STA. 446+00 (E.B. F)