

**LAW-7-2.17 PID 75923
Bedrock Core Photos**



Figure 1 – Boring B-009-1-12, Box 1 of 1. Depth 48.7' to 58.7'.



Figure 2 – Boring B-010-1-12, Box 1 of 2. Depth 29.0' to 48.2'.



Figure 3 – Boring B-010-1-12, Box 2 of 2. Depth 48.2' to 54.0'.



Figure 4 – Boring B-010-2-12, Box 1 of 2. Depth 32.0' to 48.4'.



Figure 5 – Boring B-010-2-12, Box 2 of 2. Depth 48.4' to 57.0'.



Figure 6 – Boring B-024-0-11, Box 1 of 3. Depth 15.4' to 33.6'.



Figure 7 – Boring B-024-0-11, Box 2 of 3. Depth 33.6' to 50.3'.



Figure 8 – Boring B-024-0-11, Box 3 of 3. Depth 50.3' to 51.5'.



Figure 9 – Boring B-026-0-11, Box 1 of 1. Depth 19.1' to 31.4'.



Figure 10 – Boring B-031-0-11, Box 1 of 1. Depth 11.5' to 20.0'.



Figure 11 – Boring B-032-0-11, Box 1 of 1. Depth 19.0' to 30.9'.



Figure 12 – Boring B-033-0-11, Box 1 of 1. Depth 25.4' to 35.4'.



Figure 13 – Boring B-033-1-12, Box 1 of 1. Depth 26.0' to 36.0'.



Figure 14 – Boring B-034-0-11, Box 1 of 1. Depth 25.2' to 36.2'.




Figure 15 – Boring B-035-0-11, Box 1 of 1. Depth 24.5' to 35.9'.



Figure 16 – Boring B-036-0-11, Box 1 of 1. Depth 11.0' to 31.4'.



Figure 17 – Boring B-037-1-12, Box 1 of 1. Depth 24.5' to 34.5'.



Figure 18 – Boring B-038-0-11, Box 1 of 1. Depth 36.9' to 50.6'.



Figure 19 – Boring B-039-0-11, Box 1 of 2. Depth 5.6' to 18.8'.



Figure 20 – Boring B-039-0-11, Box 2 of 2. Depth 18.8' to 21.0'.



Figure 21 – Boring B-040-0-11, Box 1 of 2. Depth 5.0' to 20.5'.



Figure 22 – Boring B-040-0-11, Box 2 of 2. Depth 20.5' to 21.3'.



Figure 23 – Boring B-050-0-11, Box 1 of 1. Depth 36.5' to 51.0'.



Figure 24 – Boring B-051-0-11, Box 1 of 2. Depth 3.1' to 19.4'.



Figure 25 – Boring B-051-0-11, Box 2 of 2. Depth 19.4' to 28.0'.



Figure 26 – Boring B-052-0-11, Box 1 of 2. Depth 4.3' to 19.7'.



Figure 27 – Boring B-052-0-11, Box 2 of 2. Depth 19.7' to 29.7'.




Figure 28 – Boring B-053-0-11, Box 1 of 5. Depth 12.5' to 26.7'.



Figure 29 – Boring B-053-0-11, Box 2 of 5. Depth 26.7' to 38.7'.



Figure 30 – Boring B-053-0-11, Box 3 of 5. Depth 38.7' to 53.7'.



Figure 31 – Boring B-053-0-11, Box 4 of 5. Depth 53.7' to 68.0'.



Figure 32 – Boring B-053-0-11, Box 5 of 5. Depth 68.0' to 80.0'.



Figure 33 – Boring B-058-0-11, Box 1 of 3. Depth 49.6' to 64.5'.



Figure 34 – Boring B-058-0-11, Box 2 of 3. Depth 64.5' to 79.0'.



Figure 35 – Boring B-058-0-11, Box 3 of 3. Depth 79.0' to 80.0'.



Figure 36 – Boring B-059-0-11, Box 1 of 5. Depth 9.8' to 24.6'.



Figure 37 – Boring B-059-0-11, box 2 of 5. Depth 24.6' to 38.6'.



Figure 38 – Boring B-059-0-11, Box 3 of 5. Depth 38.6' to 53.2'.



Figure 39 – Boring B-059-0-11, Box 4 of 5. Depth 53.2' to 67.8'.



Figure 40 – Boring B-059-0-11, Box 5 of 5. Depth 67.8' to 80.0'.



Figure 41 – Boring B-066-0-11, Box 1 of 2. Depth 15.6' to 31.6'.



Figure 42 – Boring B-066-0-11, Box 2 of 2. Depth 31.6' to 40.9'.



Figure 43 – Boring B-069-0-11, Box 1 of 9. Depth 12.3' to 26.0'.



Figure 44 – Boring B-069-0-11, Box 2 of 9. Depth 26.0' to 39.0'.



Figure 45 – Boring B-069-0-11, Box 3 of 9. Depth 39.0' to 53.5'.



Figure 46 – Boring B-069-0-11, Box 4 of 9. Depth 53.5' to 68.0'.



Figure 47 – Boring B-069-0-11, Box 5 of 9. Depth 68.0' to 83.9'.



Figure 48 – Boring B-069-0-11, Box 6 of 9. Depth 83.9' to 98.0'.



Figure 49 – Boring B-069-0-11, Box 7 of 9. Depth 98.0' to 120.7'.



Figure 50 – Boring B-069-0-11, Box 8 of 9. Depth 120.7' to 135.8'.



Figure 51 – Boring B-069-0-11, Box 9 of 9. Depth 135.8' to 145.0'.



Figure 52 – Boring B-073-0-12, Box 1 of 2. Depth 14.2' to 32.2'.



Figure 53 – Boring B-073-0-12, Box 2 of 2. Depth 32.2' to 40.2'.



Figure 54 – Boring B-086-0-12, Box 1 of 2. Depth 9.2' to 24.7'.



Figure 55 – Boring B-086-0-12, Box 2 of 2. Depth 24.7' to 40.2'.



Figure 56 – Boring B-086-1-12, Box 1 of 2. Depth 15.0' to 32.8'.



Figure 57 – Boring B-086-1-12, Box 2 of 2. Depth 32.8' to 40.0'.



Figure 58 – Boring B-087-0-12, Box 1 of 3. Depth 5.5' to 21.5'.



Figure 59 – Boring B-087-0-12, Box 2 of 3. Depth 21.5' to 38.0'.



Figure 60 – Boring B-087-0-12, Box 3 of 3. Depth 38.0' to 50.0'.



Figure 61 – Boring B-087-1-12, Box 1 of 2. Depth 24.0' to 41.0'.



Figure 62 – Boring B-087-1-12, Box 2 of 2. Depth 41.0' to 50.0'.



Figure 63 – Boring B-088-0-12, Box 1 of 3. Depth 15.1' to 38.6'.



Figure 64 – Boring B-088-0-12, Box 2 of 3. Depth 38.6' to 53.6'.



Figure 65 – Boring B-088-0-12, Box 3 of 3. Depth 53.6' to 60.1'.



Figure 66 – Boring B-091-0-12, Box 1 of 1. Depth 10.5' to 25.0'.



Figure 67 – Boring B-095-0-12, Box 1 of 2. Depth 14.0' to 32.6'.



Figure 68 – Boring B-095-0-12, Box 2 of 2. Depth 32.6' to 40.0'.



Figure 69 – Boring B-098-0-12, Box 1 of 5. Depth 11.4' to 27.1'.



Figure 70 – Boring B-098-0-12, Box 2 of 5. Depth 27.1' to 52.7'.



Figure 71 – Boring B-098-0-12, Box 3 of 5. Depth 52.7' to 70.9'.



Figure 72 – Boring B-098-0-12, Box 4 of 5. Depth 70.9' to 86.4'.



Figure 73 – Boring B-098-0-12, Box 5 of 5. Depth 86.4' to 101.4'.



Figure 74 – Boring B-098-1-12, Box 1 of 5. Depth 4.6' to 22.8'.



Figure 75 – Boring B-098-1-12, Box 2 of 5. Depth 22.8' to 38.7'.



Figure 76 – Boring B-098-1-12, Box 3 of 5. Depth 38.7' to 55.0'.



Figure 77 – Boring B-098-1-12, Box 4 of 5. Depth 55.0' to 72.5'.



Figure 78 – Boring B-098-1-12, Box 5 of 5. Depth 72.5' to 80.0'.



Figure 79 – Boring B-102-0-12, Box 1 of 3. Depth 4.5' to 25.3'.



Figure 80 – Boring B-102-0-12, Box 2 of 3. Depth 25.3' to 40.3'.



Figure 81 – Boring B-102-0-12, Box 3 of 3. Depth 40.3' to 56.0'.

B-007-2-23



Run #:	Depth		Recovery		RQD	
NQ2-1	12.5'	17.5'	34/60"	57%	4.25/60"	7%
LAW-7-2.17						

B-007-3-23



Run #:	Depth		Recovery		RQD	
NQ2-1	7.5'	12.5'	57/60"	95%	15.5/60"	26%

LAW-7-2.17

B-007-4-23



Run #:	Depth		Recovery		RQD	
NQ2-1	19.0'	22.7'	10.5/44.4"	24%	0/44.4"	0%

LAW-7-2.17

B-014-3-23



Run #:	Depth		Recovery		RQD	
NQ2-1	10.5'	15.5'	60/60"	100%	48/60"	80%
LAW-7-2.17						