

Land Slide Site BMP (State Maintained - Active): LS00010802

NLFID	SLAWSR00007**C
CRS	LAW-7-18.762
ODOT District	09
County	LAWRENCE
County CD	LAW
Route Type	State Route
Route Number	00007
Route Suffix	
CTL Begin Number	18.762
CTL End Number	18.774
STL Begin Number	18.762
STL End Number	18.774
Latitude DD Begin	38.5769920
Longitude DD Begin	-82.2949950
Latitude DD End	38.5771570
Longitude DD End	-82.2949250
PERP Date	12/30/2025
Status	Active
PID	
Let Plans URL	
Maintenance Responsibility	State
Landslide Site ID	LS00010802
Legacy GlobalID	
Road Functional Class	Other Principal Arterial Roads
Federal Aid Eligible	No
Road Width	24
Outside Shoulder Width	2
Inside Shoulder Width	0
Median Width	0
Lane Number Per Direction	1
Surface Type Left	Dense Graded Asphaltic Concrete
Surface Type Right	Dense Graded Asphaltic Concrete
Base Type Left	Aggregate Base 304 or Traffic Compacted
Base Type Right	Bituminous Concrete Mix or Penetration Macadam
Shoulder Type	Bituminous Concrete (AC)
Median Type	
Speed Limit	55
DSD - Decision Sight Distance (ft)	865
AADT Total Number	2976
Road Construction	Cut-Fill

Cardinal Direction	Yes
Driving Direction	North
Relative to Roadway	Mainline
Slope Type	Cut and Fill
Soil Origin	Fill
Soil Type	A-4a (Sandy Silt)
Associated Site Screening	LS00005923E,
Associated Site Screening Comments	Split from LS00005923 due to presence of retaining wall. Site is remediated
Info Source	Field visit
Landslide Comments	
Photo Link to Falcon	
Annual Maintenance Frequency	0
Latest Horizontal Position	
Latest Vertical Position	
Latest Average Slope Angle	
Latest Emergency Determination	
Latest Emergency Declaration Number	
Latest Emergency Declaration Date	
Latest Tier	Tier 1
Latest Detailed Rating Score	
Inspection Due	This Fiscal Year
created_user	ashelter
created_date	2/7/2022
last_edited_user	ashelter
last_edited_date	2/7/2022
sys_updated_date	7/1/2026