Query Results 1

Program Activity	Program Act. Description	Resource Description	SUM Resource Quantity/Hour s	Resourc e UM
6119	BRIDGE INSPECTION	BANASZAK KENNETH	74.00	RG
6119	BRIDGE INSPECTION			
6119	BRIDGE INSPECTION	SUTAK MICHAEL	139.50	RG
6119	BRIDGE INSPECTION	BANASZAK KENNETH	13.50	OT
6119	BRIDGE INSPECTION	PERSANYI ANDREA C	43.00	RG
6119	BRIDGE INSPECTION	EVERETT DAVID E	72.30	RG
			342.30	

TOP OFARCH

2 PEOPLE - 3 DAYS - 16 MES - 24

BOTTOM

4 PEOPLE - DAYS - 128 MRS - 160

TUHNELS
4 PEOPLE - 3 DAYS - 32 MRS

4 PEOPLE - 3 DAYS - 32 MRS

LABOR	A	В	С	D	E	F	G	Н	I	J	
1	DETAILED BREAKDOWN OF PROPO	OSED TOTAL	L HOURS,								_
2	PERSONNEL CATEGORIES, AND LA	BOR RATES	3								
3							HOURLY	RATES			
4	C/R/S VAR - DIS12 - Bridge Inspection Personnel Category							Sal	Salary Rate		
5							Project Man		\$	48.00	
6	PID NO.:	80932					Structural E		\$	35.00	
7							Engineer		\$	34.00	
8	CONSULTANT:	EUTHENIC	S INC				CADD Open	rator	\$	27.00	
9		LO IIILI II	55, 1110.				Surveyor	utoi	\$	28.00	
	DATE:	03/11/10					Printing/Cle	rical	\$	16.80	
11		00/11/10					Timing or		Ψ.	10.00	
12				1	HOURS BY	PERSONN	EL CATEG	ORY			
13			Project	Structural	TO CRES DI	CADD	EE CATEG	Printing/	Total	Labor	
14			Manager	Engineer	Engineer	Operator	Surveyor	Clerical	Hours	Costs	
	PROJECT IV - CUY-6-1456		ivianagei	Liighteer	Liighteer	Operator	Burveyor	Cicircai	Hours	Costs	
16	20101700										
17											
18	Part 1 - Bridge Inspection (In-Depth)										
19	Mobilization (III-Deptil)		1	.15	0	0	0	0	16 \$	573.00	
20	A - A - S - A - A - A - A - A - A - A -		,	. 13	0	O	O	· ·	10 0	575.00	
21	Underwater Inspection		0	2	0	0	0	0	2 \$	70.00	
22	L_		U	2	0	0	U	U	2 5	70.00	
23	Manlift		0	(2	0	0	0	0	2 \$	70.00	
24	1 vidilité		0)	0	U	· ·	2 5	70.00	
25	Physical Inspection										
26	Deck		0	12	12	0	0	0	24 \$	828.00	
27	Superstructure		0	256	256	0	0	0	512 \$	17,664.00	-
28	Substructure/Crack Monitors		0	16	16	0	0	0	32 \$	1,104.00	
29	Substituted Clack Monitors		,0	10	10	0	U	U	32 \$	1,104.00	
30	Physical Conditions Report										
31	Report		4	70	0	0	0	0	74 \$	2,642.00	
32	Plan View/Deficiency Map		0	24)	0	0	0	0	24 \$	840.00	
33	Maintenance/Rehabilitation Recommen	ndations	1	5	0	0	0	0	6 \$	223.00	
34	BR-86	il dations	0	2	0	0	0	0	2 \$	70.00	
35	2.00		0		0	Ü	0	U	2 3	70.00	
	Part 1 - Bridge Inspection (In-Depth)	Subtotal	6	404	284	0	0	0	694 \$	24,084.00	
37	Dringe inspection (in-Deptil)	Subtotal	0	704	204	0	0	U	U24 3	47,004.00	
38											
_	Part 2 - Concrete Testing										
40	Concrete Cores		0	4	0	0	0	0	4 \$	140.00	
41	Chloride Content		0	0	0	0	0	0	0 \$	140.00	
42	Choride Content		0	0	. 0	U	0	U	0 3		
	Part 2 - Concrete Testing	Subtotal	0	4	0	0	0	0	4 \$	140.00	
44	and 2 - Concrete resuing	Subtotal	U		0	0	0	U	4 3	140.00	
45											
	Part 3 - Steel Testing										
47	Ultrasonic Testing		0	4	0	0	0	0	4 S	140.00	
48	Oldasonic Testing		0	4	0	0	0	0	4 5	140.00	
	Part 3 - Steel Testing	Subtotal	0	4	0	0	0	0	4 €	140.00	
50	Part 3 - Steel Testing	Subtotal	0	4	0	U	U	U	4 \$	140.00	
51											
	PROJECT IV - CUY-6-1456		,	412	204	0	0	0		24 264 00	
34	1 NOJECT IV - CUY-0-1450		6	412	284	U	0	0	702 \$	24,364.00	

540 H25

CHECK IN

CONSULTANT BRIDGE INSPECTION AND REPORT COST SUMMARY

C/R/S:	VAR - DIS12 -	Bridge Inspection	n				ODOT Overhe	ead Percentage	=	159.01%
PID NO.: 80932 Overhead Perce					entage =		135.93%			
CONSULTANT:	EUTHENICS,	THENICS, INC.				Cost of Money =				
DATE:	03/11/10					1	Net Fee Percer	ntage =		11.00%
Task Description PROJECT IV - CUY-6-1456		Hourly Rate	Total Hours	Direct Labor Costs	Overhead Costs	Cost of Money	Other Direct Costs	Subcon. Costs	Net Fee	Total Cost
THOUSEN THE CONTROL										
Part 1 - Bridge Inspection (In-Depth) Mobilization		\$35.81	16	\$573.00	\$779.00	\$2.00	\$0.00	\$0.00	\$163.00	\$1,517.00
Underwater Inspection		\$35.00	2	\$70.00	\$95.00	\$0.00	\$0.00	\$5,501.00	\$20.00	\$5,686.00
Manlift		\$0.00	2	\$70.00	\$95.00	\$0.00	\$0.00	\$0.00	\$20.00	\$185.00
Physical Inspection Deck Superstructure Substructure/Crack Monitors		\$34.50 \$34.50 \$34.50	24 512 32	\$828.00 \$17,664.00 \$1,104.00	\$1,126.00 \$24,011.00 \$1,501.00	\$2.00 \$48.00 \$3.00	\$0.00 \$5,223.00 \$0.00	\$0.00 \$0.00 \$0.00	\$236.00 \$5,033.00 \$315.00	\$2,192.00 \$51,979.00 \$2,923.00
Physical Conditions Report Report Plan View/Deficiency Map Maintenance/Rehabilitation Recommendatio BR-86	ons	\$35.70 \$35.00 \$37.17 \$35.00	74 24 6 2	\$2,642.00 \$840.00 \$223.00 \$70.00	\$3,591.00 \$1,142.00 \$303.00 \$95.00	\$7.00 \$2.00 \$1.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$753.00 \$239.00 \$64.00 \$20.00	\$6,993.00 \$2,223.00 \$591.00 \$185.00
Part 1 - Bridge Inspection (In-Depth)	Subtotal	\$34.70 Avg. Rate	694	\$24,084.00	\$32,738.00	\$65.00	\$5,223.00	\$5,501.00	\$6,863.00	\$74,474.00
Part 2 - Concrete Testing Concrete Cores Chloride Content		\$35.00 \$0.00	4 0	\$140.00 \$0.00	\$190.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00	\$875.00 \$390.00	\$40.00 \$0.00	\$1,245.00 \$390.00
Part 2 - Concrete Testing	Subtotal	\$35.00 Avg. Rate	4	\$140.00	\$190.00	\$0.00	\$0.00	\$1,265.00	\$40.00	\$1,635.00
Part 3 - Steel Testing Ultrasonic Testing		\$35.00	4	\$140.00	\$190.00	\$0.00	\$0.00	\$525.00	\$40.00	\$895.00
Part 3 - Steel Testing	Subtotal	\$35.00 Avg. Rate	4	\$140.00	\$190.00	\$0.00	\$0.00	\$525.00	\$40.00	\$895.00
PROJECT IV - CUY-6-1456	TOTAL	\$34.71 Avg. Rate	702	\$24,364.00	\$33,118.00	\$65.00	\$5,223.00	\$7,291.00	\$6,943.00	\$77,004.00