## **PID 105793 Existing Documents**

The bridge was constructed around 1965. In 2000 the bridge received pier repair and fiber wrapping. The bridge was sub-decked in 2007. In 2011 the bridge had spalls removed from the deck.

Past construction plans can be obtained from the District 12 map room located at the district 12 office. A sampling of the following plans are located on the ODOT FTP site:

## ftp://ftp.dot.state.oh.us/pub/Districts/D12/Production/Consultant\_Programmatic/105793/

C/R/S	Year	Directory	Pages
CUY-071-17.83,	YR 1965	SD 000289	1, 309-320
CUY-071-18.48,	YR 2000	SD 000773	1-10
D-12 BH 08 Timber,	YR 2007	SD 002525	1-29
D-12 BH 2012 spall,	YR2012	SD 001300	1-42

Past Bridge inspections and current bridge inventory can be found at: http://biareports.dot.state.oh.us/