

PID 105908: CUY-BH-FY2022

Structure File Number	Bridge	Bridge Treatment Name
1800124	CUY-00002-16780-	Deck overlay(concrete) (040) Expansion joint repair/replacement (048) Deck Sealing (051) seal parapets Substructure Sealing (088) Backwall repl/repair (029) Conc patching (non-deck) (010)
1808656	CUY-00090-08340-	Deck overlay(concrete) (040) Expansion joint repair/replacement (048)
1812084	CUY-00077-14360-SW	Deck overlay(concrete) (040) Slope repair & protection installation (082) Substructure Sealing (088) Expansion joint repair/replacement (048) Deck patching(conc) (049) patch parapet Pier repl/repair (085) pier cap hatch lid replacement and fiberwrap base of non-redundant pier column Approach slab replacement/repair (100) Backwall replacement/repair (029)
1812114	CUY-00077-14370-NE	Approach slab replacement/repair (100) Backwall replacement/repair (029) Deck overlay(concrete) (040) Expansion joint repair/replacement (048) Substructure Sealing (088) Deck Sealing (051) seal parapets Slope repair & protection installation (082)
1813404	CUY-00480-22410-	Bearing reset/replaced (025) Concrete patching(non-deck) (010) Deck overlay(concrete) (040) Expansion joint repair/replacement (048) Pier replacement/repair (085) Backwall repl/repair (029) Approach slab repl/repair (100) Slope repair & protection installation (082)
2801515	GEA-00422-00170-L	Deck overlay(concrete) (040) Deck Sealing (051) seal parapets Expansion joint repair/replacement (048)