



### D12 BH FY2026 Misc (PID: 119485)

Ohio Department Of Transportation Ellis Report

User: condash  
Date: 09/14/2023

#### General Project Information

|                                     |   |   |        |
|-------------------------------------|---|---|--------|
| <b>PID:</b>                         | 119485  | <b>Project Status:</b>                              | Active |
| <b>Project Name:</b>                | D12 BH FY2026 Misc  | <b>Closed Status:</b>                               |        |
| <b>Project Type:</b>                | Let   | <b>PDP Classification:</b>                          | Path 2 |
| <b>Letting Type:</b>                | ODOT Let  | <b>Environmental Doc Type:</b>                      | C2     |
| <b>Contract Type:</b>               | Standard Build  | <b>Air Quality:</b>                                 | Exempt |
| <b>Letting Schedule (ODOT Let):</b> | Standard  | <b>District Proposal Notes / Contract Features:</b> |        |
| <b>Non Chargeable Type:</b>         |   | <b>Project Report Codes:</b>                        |        |
| <b>Work Categories:</b>             | <b>Preservation</b> <ul style="list-style-type: none"> <li>Bridge Preservation (Primary)</li> </ul> |   |        |
| <b>Description:</b>                 | Miscellaneous repairs to multiple structures in D-12.   |   |        |
| <b>Project Challenges:</b>          |   |   |        |
| <b>Split/Combine Project(s):</b>    |   |   |        |

#### Location Information

|                         |                           |                                |  |
|-------------------------|---------------------------|--------------------------------|--|
| <b>District:</b>        | D12                       | <b>Congressional District:</b> | <ul style="list-style-type: none"> <li>07</li> <li>11 (Primary)</li> <li>14</li> </ul> |
| <b>Locale:</b>          | D12                       | <b>MPO/RTPO/Large City:</b>    | <ul style="list-style-type: none"> <li>NOACA (Primary)</li> </ul>                      |
| <b>Project Termini:</b> | Various routes & sections |                                |  |

#### Project Consultant Request Information

| Request # | Programmatic Date | Consultant Request Description                                 | Linked Events Amount | Total Encumbered Amount | Shared |
|-----------|-------------------|--|----------------------|-------------------------|--------|
| 1         | 01/16/2024        | Prepare construction contract plans to repair multiple bridges | \$800,000.00         |                         | No     |

#### Project Bridge Information

| SFN     | Dist | Residing Location        | Intersecting Location    | Primary Location         | SD | Feature Intersected      | Treatment(s)  | Municipality         | Project Classification |
|---------|------|--------------------------|--------------------------|--------------------------|----|--------------------------|---|----------------------|------------------------|
| 1814907 | 12   | SCUYUS00422**N<br>16.089 |                          | SCUYUS00422**N<br>16.089 | L  | CR-18 (HARPER RD)        | <ul style="list-style-type: none"> <li>Deck Patching - Concrete</li> <li>Steel Repair</li> <li>Pier Repair</li> <li>Slope Repair &amp; Protection</li> </ul>  | SOLOON               | N F 17668              |
| 1814923 | 12   | SCUYUS00422**N<br>17.706 | SCUYSR00091**C<br>02.860 | SCUYUS00422**N<br>17.706 | L  | SR 91 SOM CENTER RD      | <ul style="list-style-type: none"> <li>Deck Patching - Concrete</li> <li>Bearing Reset</li> <li>Steel Repair</li> <li>Abutment Repair</li> <li>Pier Repair</li> <li>Approach Slab Replacement</li> <li>Slope Repair &amp; Protection</li> <li>Railing Repair</li> </ul> | SOLOON               | N F 17668              |
| 1814788 | 12   | SCUYUS00422**N<br>13.712 | SCUYSR00175**C<br>02.369 | SCUYUS00422**N<br>13.712 | L  | SR 175(02.35)RICHMOND RD | <ul style="list-style-type: none"> <li>Deck Patching - Concrete</li> <li>Abutment Repair</li> <li>Backwall Repair</li> <li>Pier Repair</li> <li>Substructure Sealing</li> <li>Slope Repair &amp; Protection</li> </ul>  | WARRENSVILLE HEIGHTS | N F 17668              |
| 1814915 | 12   | SCUYUS00422**C<br>16.175 |                          | SCUYUS00422**C<br>16.175 | R  | CR-18 (HARPER RD)        | <ul style="list-style-type: none"> <li>Deck Patching - Concrete</li> <li>Steel Repair</li> <li>Pier Repair</li> <li>Slope Repair &amp; Protection</li> </ul>  | SOLOON               | N F 17668              |
| 1814745 | 12   | SCUYUS00422**C<br>13.823 | SCUYSR00175**C<br>02.341 | SCUYUS00422**C<br>13.823 | R  | SR 175 (RICHMOND RD)     | <ul style="list-style-type: none"> <li>Deck Patching - Concrete</li> <li>Abutment Repair</li> <li>Backwall Repair</li> <li>Pier Repair</li> <li>Substructure Sealing</li> <li>Slope Repair &amp; Protection</li> </ul>  | WARRENSVILLE HEIGHTS | N F 17668              |
| 1814885 | 12   | SCUYUS00422**N<br>15.816 |                          | SCUYUS00422**N<br>15.816 | L  | CR-99 (CANNON RD)        | <ul style="list-style-type: none"> <li>Deck Patching - Concrete</li> <li>Expansion Joint Replacement</li> </ul>   | SOLOON               | N F 17668              |

| SFN     | Dist | Residing Location        | Intersecting Location    | Primary Location         | SD | Feature Intersected      | Treatment(s)   | Municipality         | Project Classification |
|---------|------|--------------------------|--------------------------|--------------------------|----|--------------------------|--|----------------------|------------------------|
|         |      |                          |                          |                          |    |                          | <ul style="list-style-type: none"> <li>• Steel Repair</li> <li>• Abutment Repair</li> <li>• Backwall Repair</li> <li>• Slope Repair &amp; Protection</li> </ul>  |                      |                        |
| 1814893 | 12   | SCUYUS00422**C<br>15.871 |                          | SCUYUS00422**C<br>15.871 | R  | CR-99 (CANNON RD)        | <ul style="list-style-type: none"> <li>• Deck Patching - Concrete</li> <li>• Expansion Joint Replacement</li> <li>• Steel Repair</li> <li>• Abutment Repair</li> <li>• Backwall Repair</li> <li>• Slope Repair &amp; Protection</li> </ul> | SOLON                | N F 17668              |
| 1814931 | 12   | SCUYUS00422**C<br>17.783 | SCUYSR00091**C<br>02.850 | SCUYUS00422**C<br>17.783 | R  | SR 91 SOM CENTER RD      | <ul style="list-style-type: none"> <li>• Bearing Reset</li> <li>• Steel Repair</li> <li>• Approach Slab Replacement</li> <li>• Slope Repair &amp; Protection</li> </ul>  | SOLON                | N F 17668              |
| 1814753 | 12   | SCUYRA18303**C<br>00.507 | SCUYSR00175**C<br>02.331 | SCUYRA18303**C<br>00.507 | WE | SR 175 (RICHMOND RD)     | <ul style="list-style-type: none"> <li>• Abutment Repair</li> <li>• Backwall Repair</li> <li>• Substructure Sealing</li> </ul>   | WARRENSVILLE HEIGHTS | N F 17668              |
| 2801558 | 12   | TGEATR00188**C<br>00.153 | SGEAUS00422**C<br>00.263 | SGEAUS00422**C<br>00.263 |    | USR 422 ALT (0026)       | <ul style="list-style-type: none"> <li>• Bearing Replacement</li> <li>• Steel Repair</li> </ul>  |                      | N F 17668              |
| 2801779 | 12   | SGEAUS00422**C<br>12.285 |                          | SGEAUS00422**C<br>12.285 |    | CUY. RIV. 0.78 MI. W 700 | <ul style="list-style-type: none"> <li>• Deck Sealing - Gravity Fed Resin</li> </ul>   |                      | N P 99999              |