



SFN 4303938
LAK-090-0645R

EROSION TO FORWARD-RIGHT
EMBANKMENT



CLOSE UP