

# **OHIO DEPARTMENT OF TRANSPORTATION**

Central Office • 1980 West Broad Street • Columbus, OH 43223 John R. Kasich, Governor • Jerry Wray, Director

1/27/2015

Project 150051 Addendum No. 2 PID No. 92207 SHE – SR 29 – 14.63 Bridge Repair Letting: January 29, 2015

Notice to all Bidders and Suppliers to please be advised of the attached Proposal Addendum.

The Department utilizes Bid Express (<u>http://www.bidx.com</u>) as the official medium for electronic bid submittal. All bidders must prepare bids and submit them online via Bid Express.

Addenda amendments must be acknowledged in the miscellaneous section of the Expedite (EBS) file and all amendments loaded in order for your bid to be considered for award of this project. Bid express will not accept bids that do not have amendments incorporated. Failure to incorporate changed quantities or items in your Expedite (EBS) submissions will result in the rejection of your bid.

# Proposal Addendum For SHE-29-14.63; PID 92207 Project 150051

## **Completion Date Change:** No

## **Bid Item Changes, Additions or Deletions:** Yes

Funding Splits Required: No

## **Revised Bid Items:**

Ref. No.	Item No.	Total Quantity	Unit	Description	Section
51	630E07600	136	FT	GROUND MOUNTED STRUCTURAL BEAM SUPPORT, W10X12	5

## Please be advised of the following:

Addendum provides revision to item extension and description for ground mounted structural beam support.

# Add the following Note: No

## Plan sheets added, deleted or replaced: No

## **Plan sheet revisions:** Yes

- 1. Sheet 41/144 General Summary. Revised item extension and description per the above for ground mounted beam support (formerly ground mounted structural beam support, W10x22).
- 2. Sheet 41/144 Traffic Control Summary. Revised description per the above for ground mounted beam support (formerly ground mounted structural beam support, W10x22).

## **Answers to Prebid Questions:** Yes

## Q1: Submitted 1/27/15 @ 7:36 AM

Plan sheets 118-120 detail a W10x12 beam sign support. Sub-summary sheet 110 and proposal lists a W10x22 beam size. Which should we use?

A1: The sign details sheets are correct, they should be W10x12 on the subsummary and general summary also.