





















TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-001-0-20	Mid-lane	40.401241, -81.324825	Asphalt 11.0 Concrete 8.0		
B-002-0-20	Mid-lane	40.401887, -81.324164	Asphalt 15.0 Concrete 8.0		
B-003-0-20	Mid-lane	40.402608, -81.323124	Asphalt 14.0 Concrete 8.0		
B-004-0-20	Mid-lane	40.403178, -81.321879	Asphalt 15.0 Concrete 7.0		
B-005-0-20	White Line	40.403498, -81.320549	Asphalt 8.0		
B-006-0-20	White Line	40.404062, -81.319307	Asphalt 9.0		
B-007-0-20	Mid-lane	40.404842, -81.318323	Asphalt 15.0 Concrete 7.0		








TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-008-0-20	Mid-lane	40.405878, -81.317692	Asphalt 14.0 Concrete 7.0		
B-009-0-20	Mid-lane	40.406741, -81.317098	Asphalt 14.0 Concrete 7.0		
B-010-0-20	Mid-lane	40.407599, -81.316158	Asphalt 15.0 Concrete 7.0		
B-011-0-20	Mid-lane	40.408067, -81.314935	Asphalt 18.0 Concrete 6.0		
B-012-0-20	White Line	40.408283, -81.313539	Asphalt 12.0		
B-013-0-20	White Line	40.408078, -81.31214	Asphalt 12.0		
B-014-0-20	Mid-lane	40.407794, -81.310798	Asphalt 15.0 Concrete 7.0		








TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-015-0-20	Mid-lane	40.4071, -81.309683	Asphalt 13.0 Concrete 8.0		
B-016-0-20	Mid-lane	40.406315, -81.308797	Asphalt 13.0 Concrete 8.0		
B-017-0-20	Mid-lane	40.405389, -81.307955	Asphalt 13.0 Concrete 8.0		
B-018-0-20	Mid-lane	40.404588, -81.307088	Asphalt 14.0 Concrete 7.0		
B-019-0-20	White Line	40.403669, -81.3062	Asphalt 6.0		
B-020-0-20	White Line	40.403131, -81.304987	Asphalt 11.0		
B-021-0-20	Mid-lane	40.402818, -81.303609	Asphalt 11.0 Concrete 6.0		








TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-022-0-20	Mid-lane	40.402956, -81.302212	Asphalt 13.5 Concrete 7.5		
B-023-0-20	Mid-lane	40.403379, -81.300916	Asphalt 13.5 Concrete 7.5		
B-024-0-20	Mid-lane	40.403937, -81.299692	Asphalt 13.0 Concrete 7.0		
B-025-0-20	Mid-lane	40.404485, -81.298493	Asphalt 13.5 Concrete 7.5		
B-026-0-20	White Line	40.405331, -81.297498	Asphalt 8.0		
B-027-0-20	White Line	40.406067, -81.296468	Asphalt 12.0		
B-028-0-20	Mid-lane	40.406901, -81.295527	Asphalt 14.0 Concrete 6.0		







TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-029-0-20	Mid-lane	40.407635, -81.294534	Asphalt 14.0 Concrete 8.0		
B-030-0-20	Mid-lane	40.408473, -81.293576	Asphalt 21.0		
B-031-0-20	Mid-lane	40.409151, -81.292524	Asphalt 13.5 Concrete 6.5		
B-032-0-20	Mid-lane	40.409673, -81.291244	Asphalt 13.5 Concrete 8.0		
B-033-0-20	Mid-lane	40.409785, -81.289898	Asphalt 13.0 Concrete 7.0		
B-034-0-20	White Line	40.409661, -81.288454	Asphalt 8.0		
B-035-0-20	Mid-lane	40.409254, -81.287065	Asphalt 12.5 Concrete 7.5		

TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-036-0-20	Mid-lane	40.40897, -81.285771	Asphalt 13.0 Concrete 8.0		
B-037-0-20	Mid-lane	40.408487, -81.284473	Asphalt 13.0 Concrete 8.0		
B-038-0-20	Mid-lane	40.408053, -81.283196	Asphalt 13.0 Concrete 8.0	No Photo	
B-039-0-20	Mid-lane	40.407512, -81.281927	Asphalt 14.0 Concrete 7.0		
B-040-0-20	White Line	40.406983, -81.280759	Asphalt 12.0		
B-041-0-20	White Line	40.406055, -81.279956	Asphalt 8.0		
B-042-0-20	Mid-lane	40.405153, -81.279285	Asphalt 13.5 Concrete 7.5		
B-043-0-20	Mid-lane	40.404149, -81.278694	Asphalt 14.0 Concrete 7.0		

TUS-250-23.46 PID 102408
PAVEMENT CORE REPORT

Location	Position	Lat/Long	Pavement Thickness (in)	Core Photo	Comments
B-044-0-20	Mid-lane	40.403244, -81.278054	Asphalt 14.0 Concrete 7.0		
B-045-0-20	Mid-lane	40.402186, -81.277327	Asphalt 13.0 Concrete 7.0		
B-046-0-20	Mid-lane	40.401502, -81.27627	Asphalt 13.0 Concrete 8.0		
B-047-0-20	White Line	40.400836, -81.275104	Asphalt 9.0		
B-048-0-20	White Line	40.400296, -81.273881	Asphalt 9.0		
B-049-0-20	Mid-lane	40.399649, -81.272737	Asphalt 12.0 Concrete 7.0		
B-050-0-20	Mid-lane	40.399081, -81.271534	Asphalt 12.5 Concrete 7.0	