

Horizontal Alignment Review Report

Report Created: Monday, July 15, 2024
Time: 9:30:20 AM

Project: Design

Description:

File Name: c:\users\jmille21\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\jeffery.miller@dot.ohio.gov\d1076271\101291_BK001.dgn

Last Revised: 7/15/2024 09:29:57

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: CLXRW_S065_101291-WOO-20-12.34

Alignment Description:

Alignment Style: Alignment\RW_X_Centerline

		Station	Northing	Easting
Element: Linear				
REF43	POT (POT)	618+28.80 R1	487432.420	217789.703
REF47	HPI (HPI)	678+74.84 R1	484569.940	223115.189
	Tangential Direction:	S61.742°E		
	Tangential Length:	6046.04		
Element: Linear				
REF47	HPI (HPI)	678+74.84 R1	484569.932	223115.163
SANREF1	HPI (HPI)	0+00.00 R2	481663.725	228444.167
	Tangential Direction:	S61.394°E		
	Tangential Length:	6069.95		
Element: Linear				
SANREF1	HPI (HPI)	0+00.00 R2	481663.725	228444.167
	EQNBK	739+44.79 R1	481663.725	228444.167
	EQNAHD	0+00.00 R2	481663.725	228444.167
SANREF3C	HPI (HPI)	56+36.17 R2	478964.345	233391.873
	Tangential Direction:	S61.384°E		
	Tangential Length:	5636.17		
Element: Linear				
SANREF3C	HPI (HPI)	56+36.17 R2	478964.345	233391.873
SANREF5	POT (POT)	118+12.64 R2	476028.790	238826.145
	Tangential Direction:	S61.622°E		
	Tangential Length:	6176.47		