



7995 Allen Road
Canal Winchester, OH 43110
P: (614) 837-3010

Surveyors name: William Slane Certificate Number: 06022715 System Owner: City Of Columbus Survey Customer: MS Consultants Drainage Area: Sheet: 1

P/O No.: Pipeline Segment Reference: D:E Date: 3/27/2020 Time: 10:40 AM Location (Street Name and number): Mound St Locality: Columbus

Further Location details: Road Upstream Manhole Number: D Rim to Invert: Grade to Invert: Rim to Grade:

Downstream Manhole Number: E Rim to Invert: Grade to Invert: Rim to Grade: Use of Sewer: Sanitary Direction: Downstream Flow Control: N Height: 15

Width: Shape: Circular Material: PVC Ln. Method: Pipe Joint Length: Total Length: Length Surveyed: Year Laid: Year Rehabilitated: Tape / Media Number:

Purpose: F Sewer Category: Pre-Cleaning: No Pre-Cleaning Cleaned: Weather: Dry Additional Information:

Distance (Feet)	Code		Continuous defect	Value			Joint	Circumferential Location		Image Ref.	Struct. Grade	O&M Grade	Remarks	
	Group/ Descriptor	Modifier/ severity		S/M/L	Inches			%	At / From					To
					1st	2nd								
0.0	AMH									D_E_@0			Starting Manhole: D	
0.0	MWL					5				D_E_@0_1				
64.7	AMH									D_E_@64.7				Ending MH: E

Segment	Structural								O & M								Overall							
	Grade 1	Grade 2	Grade 3	Grade 4	Grade 5	Rating	Quick	Index	Grade 1	Grade 2	Grade 3	Grade 4	Grade 5	Rating	Quick	Index	Grade 1	Grade 2	Grade 3	Grade 4	Grade 5	Rating	Quick	Index
D_E_3 27 2020	0	0	0	0	0	0	0000		0	0	0	0	0	0	0000		0	0	0	0	0	0	0000	



7995 Allen Road
Canal Winchester, OH 43110
P: (614) 837-3010



Upstream MH: D
Surveyor's Name: William Slane
System Owner: City Of Columbus
Drainage Area:
 City: Columbus
Pipe Segment Ref.: D:E
 Sewer Use: Sanitary
 Flow Control: Not controlled
 Material: Polyvinyl Chloride
Media Number:
 Pre-Cleaning: No Pre-Cleaning
 Date: 3/27/2020
 Time: 10:40 AM
 Cleaned:
 Year Laid:
 Year Rehab.:
Additional Information:

Downstream MH: E
Certificate Number: 06022715
Survey Customer: MS Consultants
Purchase Order #:
 Street Address: Mound St
 Location Details: Road
 Direction: Downstream
 Shape: Circular
 Ln. Method:
 Purpose: Routine Assessment
 Weather: Dry
Height: 15
 Width:
 Joint Length:
 Total Length:
 Len. Surveyed:
Measurements: **U/D**
 Rim to Invert: /
 Grade to Invert: /
 Rim to Grade: /
 Sewer Category:

