

Map Check Report

Report Created: Friday, July 18, 2025
Time: 10:27:48 AM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0329192\114957_BR002.dgn

Last Revised: 7/18/2025 10:26:12

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 10-SH1

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S7.385°W	235.000		
HPI	(HPI)	-233.051	-30.206	0.000
	N82.615°W	30.000		
HPI	(HPI)	-229.195	-59.957	0.000
	N32.087°W	110.120		
HPI	(HPI)	-135.896	-118.453	0.000
	N7.385°E	65.000		
HPI	(HPI)	-71.435	-110.098	0.000
	N46.857°E	110.110		
HPI	(HPI)	3.860	-29.756	0.000
	S82.615°E	30.000		
POT	(POT)	0.004	-0.005	0.000

Northing Error: 0.004 ft
Easting Error: -0.005 ft
Closing Direction: S51.295°E
Closing Distance: 0.006 ft
Closed Area: 17550.856 sq ft 0.403 ac
Perimeter: 580.230 ft
Precision: 96799 : 1