

Map Check Report

Report Created: Friday, July 18, 2025
Time: 10:30:29 AM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0329192\114957_BR002.dgn

Last Revised: 7/18/2025 10:29:10

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 11-SH3

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S82.615°E	30.000		
HPI	(HPI)	-3.856	29.751	0.000
	S28.869°E	93.010		
HPI	(HPI)	-85.307	74.657	0.000
	S7.385°W	45.930		
HPI	(HPI)	-130.856	68.753	0.000
	S89.672°W	85.780		
HPI	(HPI)	-131.347	-17.025	0.000
	N7.385°E	132.450		
POT	(POT)	0.004	-0.001	0.000

Northing Error: 0.004 ft
Easting Error: -0.001 ft
Closing Direction: S8.841°E
Closing Distance: 0.004 ft
Closed Area: 8706.432 sq ft 0.200 ac
Perimeter: 387.170 ft
Precision: 92289 : 1