

Map Check Report

Report Created: Friday, July 18, 2025
Time: 10:55:54 AM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0329192\114957_BR002.dgn

Last Revised: 7/18/2025 10:54:38

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 11-SH3

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
PC	(PC)	0.000	0.000	0.000
	S83.529°E	819.020		
CC	(CC)	-92.307	813.802	0.000
	S82.615°E	819.020		
PT	(PT)	12.965	1.575	0.000
	N7.385°E	113.070		
HPI	(HPI)	125.097	16.109	0.000
	N89.672°E	85.780		
HPI	(HPI)	125.587	101.887	0.000
	S24.285°W	137.490		
HPI	(HPI)	0.264	45.341	0.000
	S89.672°W	45.340		
POT	(POT)	0.005	0.001	0.000

Northing Error: 0.005 ft
Easting Error: 0.001 ft
Closing Direction: S16.075°W
Closing Distance: 0.005 ft
Closed Area: 8201.018 sq ft 0.188 ac
Perimeter: 394.740 ft
Precision: 83396 : 1