

Map Check Report

Report Created: Friday, July 18, 2025
Time: 11:04:52 AM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0329192\114957_BR002.dgn

Last Revised: 7/18/2025 10:57:09

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 11-U1

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
PC	(PC)	0.000	0.000	0.000
	S89.225°E	789.020		
CC	(CC)	-10.675	788.948	0.000
	S83.269°E	789.020		
PT	(PT)	81.804	5.366	0.000
	N89.672°E	15.120		
HPI	(HPI)	81.891	20.486	0.000
	S14.042°W	84.420		
POT	(POT)	-0.007	0.003	0.000

Northing Error: -0.007 ft
Easting Error: 0.003 ft
Closing Direction: N25.558°W
Closing Distance: 0.008 ft
Closed Area: 676.638 sq ft 0.016 ac
Perimeter: 181.557 ft
Precision: 24064 : 1