

Map Check Report

Report Created: Friday, July 18, 2025
Time: 11:12:27 AM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0329192\114957_BR002.dgn

Last Revised: 7/18/2025 11:11:19

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 11-U4

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	N7.385°E	73.520		
HPI	(HPI)	72.910	9.450	0.000
	N89.728°E	15.130		
HPI	(HPI)	72.982	24.580	0.000
	S1.831°E	124.870		
HPI	(HPI)	-51.824	28.570	0.000
	N28.869°W	59.190		
POT	(POT)	0.010	-0.007	0.000

Northing Error: 0.010 ft
Easting Error: -0.007 ft
Closing Direction: S34.446°E
Closing Distance: 0.012 ft
Closed Area: 2230.732 sq ft 0.051 ac
Perimeter: 272.710 ft
Precision: 22313 : 1