



Surveying And Mapping, LLC (SAM)
 929 Eastwind Drive, Suite 201
 Westerville, Ohio 43081
 Office: 614-899-0079

**SUE QUALITY LEVEL A
 ABANDONED SANITARY
 EXPLORATION
 TOLEDO, OHIO**

Project:	LUC 25 ANTHONY WAYNE TRAIL	Date Performed:	10/12/2022
SAM, LLC Project #	1022073581	Client:	Ohio Department of Transportation
Project Location:	LUCAS COUNTY	Surface Material	NATURAL GROUND
Utility Location:	3223 ERAWA DR	Surface Elevation:	N/A
Utility Sta./Offset:	N/A	Surface Condition:	POOR
Record Utility:	ABANDONED SANITARY	Trench Material:	SOIL
Utility Owner:	CITY OF TOLEDO	Utility Bedding Material:	N/A
Contact:	N/A	Utility Found:	N/A
Phone/Email:	N/A	Utility Condition:	N/A
Field Crew:	JN/NB	Utility Depth (Top):	N/A
Field Conditions:	SUNNY/COLD		



PROJECT CONTROL

Coordinates shown are based on Ohio State Plane NAD 83, South Zone, Grid, derived from GPS observations utilizing the Trimble Network.

UTILITY CENTERLINE COORD.

NORTHING	N/A
EASTING	N/A
TOP ELEV.	N/A

Comments

1. SAM field crews performed GPR designating, test hole trenching exploration, probing, and other locating methods to try and locate the abandoned sanitary line as explained by the client. No evidence was found of the abandoned line.
2. No other utilities were found during excavation
3. All excavation was performed with VAC truck
4. The Test Hole was backfilled with Excavated Material.
5. Location and elevation determined by satellite observations utilizing ODOT VRS.