

Horizontal Alignment Review Report

Report Created: Tuesday, February 13, 2024
Time: 6:46:26 AM

Project: Design

Description:

File Name: c:\users\jmille21\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\jeffery.miller@dot.ohio.gov\d0881229\119896_BK001.dgn

Last Revised: 2/13/2024 06:43:47

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: BLX_S19_119896-SAN-19-2.72

Alignment Description:

Alignment Style: Alignment\GE_X_Alignment

| | <u>Station</u> | <u>Northing</u> | <u>Easting</u> |
|-----------------------|----------------|-----------------|----------------|
| Element: Linear | | | |
| BL1 POT (POT) | 0.000 | 289908.553 | 177334.494 |
| BL2 POT (POT) | 599.818 | 290505.704 | 177277.994 |
| Tangential Direction: | N5.405°W | | |
| Tangential Length: | 599.818 | | |