

O.D.O.T. DISTRICT 2 SURVEY OFFICE (USE ONLY)

PERSONNEL _____

REFERENCE NO. _____

SHEET 4 OF 34

NOTES VAN DUSEN

DATE 1/30/98

ROUTE I-75

H.C. MOSE

WEATHER CLOUDY

COUNTY LUCAS

R.C. HUSS

TEMP. 35°

TOWNSHIP CITY OF TOLEDO

SECTION 17

DWG BY NIESE

PID _____

T 9 S R 8 E

TYPE MONUMENT 1/4" DRILL HOLE

ON SURFACE - ~~BELOW~~ ON

OFFSET 0.07' ± : RT

- TO - EDGE PAVEMENT


STATION: 420+00.46

HORIZ. DATUM: _____

GEOID: _____

GRID: NORTHING: _____

EASTING: _____



RECORD:
1/4" DRILL HOLE
IN RETAINING WALL
ORIGINAL POSITION OF
MONBOX SET PRE-CONST.
PT#1040
N: 42908.534
E: 38795.613
1/30/98, VAN DUSEN

☉ SB I-75

☉ NB I-75

DIST. PT#1041-PT#1040=0.46'

●
●
PT#1041

CONCRETE MEDIAN

PERSONNEL	TITLE	PERSONNEL	TITLE
VAN DUSEN			
MOSEY			
HUFF			

COUNTY LUCAS DATE 1-30-98
 S.B. I-75 WEATHER CLOUDY
 SEC. 7.83 TEMP. +35° F

DESCRIPTION CONFIRMATION & LOCATION OF MONUMENTS JOB NO. 023350
 LEFT CENTER LINE RIGHT

