

O.D.O.T. DISTRICT 2 SURVEY OFFICE (USE ONLY)

PERSONNEL _____

REFERENCE NO. _____

SHEET 8 OF 34

NOTES VAN DUSEN

DATE 1/30/98

ROUTE I-75

H.C. MOSER

WEATHER CLOUDY

COUNTY LUCAS

R.C. HUSS

TEMP. 35°

TOWNSHIP CITY OF TOLEDO

SECTION 17

DWG BY NIESE PID _____

T 9 S R 8 E

TYPE MONUMENT 1/4" DRILL HOLE

ON SURFACE - ~~BELOW~~ ON

OFFSET \odot PAVEMENT 0.10' \pm : RT

- TO - EDGE PAVEMENT


STATION: 435+00.10

HORZ. DATUM: _____

GEOID: _____

GRID: NORTHING: _____

EASTING: _____



RECORD:
1/4" DRILL HOLE
IN CONC WALL
ORIGINAL POSITION OF
MONBOX PRE-CONST.
PT#1036
N: 44368.347
E: 38452.803
1/30/98, VAN DUSEN

\odot SB I-75

\odot NB I-75

DIST. PT#1035-PT#1036=0.11'

CONCRETE MEDIAN

\bullet
 \bullet
PT#1035

PERSONNEL	TITLE	PERSONNEL	TITLE
VAN DUSEN			
MOSEY			
HUFF			

COUNTY LUCAS DATE 1-30-98
 S.B. I-75 WEATHER CLOUDY
 SEC. 7.83 TEMP. +35° F

DESCRIPTION CONFIRMATION & LOCATION OF MONUMENTS JOB NO. 023350
 LEFT CENTER LINE RIGHT

