

O.D.O.T. DISTRICT 2 SURVEY OFFICE (USE ONLY)

PERSONNEL

REFERENCE NO. \_\_\_\_\_

SHEET 12 OF 34

NOTES VAN DUSEN

DATE 1/30/98

ROUTE I-75

H.C. MOSER

WEATHER CLOUDY

COUNTY LUCAS

R.C. HUSS

TEMP. 35°

TOWNSHIP CITY OF TOLEDO

DWG BY NIESE PID \_\_\_\_\_

SECTION 8

T 9 S R 8 E

TYPE MONUMENT 1/4" DRILL HOLE

ON SURFACE - BELOW ON

OFFSET  $\odot$  PAVEMENT \_\_\_\_\_ LT : RT

- TO - EDGE PAVEMENT


STATION: 457+29

HORZ. DATUM: \_\_\_\_\_

GEOID: \_\_\_\_\_

GRID: NORTHING: \_\_\_\_\_

EASTING: \_\_\_\_\_



RECORD:  
1/4" DRILL HOLE  
IN RETAINING WALL  
PT#1022  
N: 46530.931  
E: 38005.625  
1/30/98, VAN DUSEN

$\odot$  SB I-75

$\odot$  NB I-75

CONCRETE MEDIAN

CONC. RETAINING WALL

$\bullet$  1/4" DRILL HOLE  
IN CONC WALL

PERSONNEL	TITLE	PERSONNEL	TITLE
VAN DUSEN			
MOSEK			
HUSS			

COUNTY LUCAS DATE 1-30-98  
 S.R. I-75 WEATHER CLOUDY  
 SEC. 2.83 TEMP. +35°F

DESCRIPTION CONFIRMATION & LOCATION OF MONUMENTS JOB NO. 023350  
 LEFT CENTER LINE RIGHT

