

O.D.O.T. DISTRICT 2 SURVEY OFFICE (USE ONLY)

PERSONNEL _____

REFERENCE NO. _____

SHEET 16 OF 34

NOTES VAN DUSEN DATE 1/30/98
 H.C. MOSER WEATHER CLOUDY
 R.C. HUSS TEMP. 35°

ROUTE I-75
 COUNTY LUCAS
 TOWNSHIP CITY OF TOLEDO
 SECTION 8
 T 9 S R 8 E

DWG BY NIESE PID _____

TYPE MONUMENT 1/4" DRILL HOLE

ON SURFACE - ~~BELOW~~ ON _____


OFFSET \varnothing PAVEMENT _____ LT : RT

- TO - EDGE PAVEMENT

STATION: 468+55

HORZ.DATUM: _____ GEOID: _____

GRID: NORTHING: _____ EASTING: _____



RECORD:
 1/4" DRILL HOLE
 IN RETAINING WALL
 PT#1024
 N: 47621.489
 E: 37749.579
 1/30/98, VAN DUSEN

\varnothing SB I-75

\varnothing NB I-75

CONCRETE MEDIAN

CONC. RETAINING WALL

● 1/4" DRILL HOLE
 IN CONC WALL

PERSONNEL	TITLE	PERSONNEL	TITLE
VAN DUSEN			
MOSEK			
HUSS			

COUNTY LUCAS DATE 1-30-98
 S.R. I-75 WEATHER CLOUDY
 SEC. 2.83 TEMP. +35°F

DESCRIPTION CONFIRMATION & LOCATION OF MONUMENTS JOB NO. 023350
 LEFT CENTER LINE RIGHT

