



**Photo 1: Lack of pedestrian infrastructure along S. 11<sup>th</sup> Street (Goat Path)**

*Source: OMEGA*



**Photo 2: Existing infrastructure along the corridor that is in poor condition.** *Source: OMEGA*



**Photo 3: Current development along the corridor may result in utility relocation.**

*Source: OMEGA*



Photo 4: Evidence of use by pedestrians currently.

Source: OMEGA