




4-10-78

TO
GUE-77-0943A Damage From Hit

4-10-78



Bm # 1 Stiffener
Rear of Impact



Bm # 1
Flange



Bm # 2
Bottom Flange



Bm # 1 Left
Looking Right

1978



Bm #1 Stiffener
on Inside



Bm #2
Bottom Flange




Bm #1 Outside
Bent Stiffener Bent
Bottom Flange



Bm #1
Flange



Bm #2
Bottom Flange



Bm #2
Bottom Flange

1978