FRA-161-15.80							
Stage 3 Backcheck - 4th Review Comments					RESPONSE	LEGEND	
City of Columbus Project #:					A: AGREE FULLY, revised per comment		
only or columbus region //.					B: AGREE PARTLY, EXCEPTIONS NOTED		
ODOT PID #:	ID#: 117607				C: DISAGREE FULLY, REASONS NOTED		
					D: COMMENT HAS BEEN SUPERSEDED BY DESIGN DEVELOPMENT E: QUESTION ONLY, ANSWER PROVIDED		
Date:	Note to consultant: Comment completed and verified by Jeff Hackenbracht -6-06-2024				E: QUESTION ONLY, ANSWER PROVIDED F: NO ACTION REQUIRED		
NO.	SHEET NO	COLOR	COMMENTS	COMMENT BY	ACTION REQ'D A,B,C, D,E,F	QUESTIONS/RESPONSE TO CITY	CURRENT STATUS (OPEN/CLOSED)
			PLANS				
1	58	#N/A	Are these elevations correct?	dahill	Е	Elevations were provided by SAM. Please refer to the utility note for the complete results of their investigation.	
2	4	#N/A	There is no 100-year Floodplain line on this side.	rmvansickle	Α	Complied.	
3	4	#N/A	The Floodway line is the line I have marked blue. Please correct it.	rmvansickle	Α	Complied.	
4	49	#N/A	Repeat Comment. Just Floodway through here.	rmvansickle	Α	Complied.	
5	49	#N/A	Floodway isn't this line. It is the next line to the left.	rmvansickle	Α	Complied.	
6	49	#N/A	Repeat Comment. Only Floodway here.	rmvansickle	Α	Complied.	
7	49	#N/A	Only Floodway here. No 100-year Floodplain line here.	rmvansickle	Α	Complied.	
8	1	#N/A	Please see minor floodplain comments & questions on p. 4 & 49. Renee VanSickle, 5-29-2024.	rmvansickle	A	Complied.	
9	58	#N/A	The required 3'-0" minimum horizontal separation is not being met here. It is evident that you are centering the maximum sized panel over the existing 12" water main in an attempt to provide as much horizontal separation that the current alignment can provide. However you are only providing approximately 9"-11" of horizontal clearance (out-to-out), which is not sufficient. Please revisit your current design and alignment to meet this separation requirement. Please verify & revise accordingly.	dahill	A	Complied by revising the alignment to provide the required 3'-0" min horizontal separation.	
			Drainage Report				
40	4	Delate Con	O'ex and Ord			0	
10	1	Bright Green	Sign and Seal		A	Complied	