



HAM 126 17.53 SFN: 3105067 SR126 over Eldorado Str.
Remove loose concrete in span 1 or west span over sidewalk.
Close to Column 6, counting from north to south.



05/01/2024

HAM 126 17.53 SFN: 3105067 SR126 over Eldorado Str.

Remove loose concrete in span 1 or west span over sidewalk. Close to north edge.



05/01/2024

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.
Remove loose concrete in span 2, along median area in center of
span over SB lane.



05/01/2024

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.

Remove loose concrete in span 2, along median area in center of span over SB lane.




05/01/2024

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.

Remove loose concrete in span 2, several areas close to col. 6 of pier 1 over SB lane.



05/01/2024



HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.

Remove loose concrete in span 2, along median area (in center of span) and in front of pier 2, over NB lane/shoulder.

05/01/2024

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.

Remove loose concrete in span 2, under WB lanes of SR126 over NB lane of Eldora Str.

05/01/2024

A photograph of a concrete surface, likely a bridge deck. The surface is grey and shows signs of wear, including several small, dark, circular marks (possibly rebar heads or holes) and a prominent vertical crack running down the center. A red circle is drawn around a specific area of the concrete, highlighting a crack and some discoloration. A white text box is overlaid on the left side of the image, and a date stamp is in the bottom right corner.

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.
Remove loose concrete in span 2, under WB lanes of
SR126 over NB lane of Eldora Str.

05/01/2024

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.

Remove loose concrete in span 2, under WB lanes of SR126 over NB lane of Eldora Str.

05/01/2024

A photograph of a concrete surface, likely a bridge deck or sidewalk, showing signs of wear and damage. A prominent horizontal crack runs across the middle of the frame. To the left of this crack, there is a smaller, irregularly shaped area of damaged concrete, which is circled in red. The concrete surface is light gray and shows numerous small, dark brown spots, possibly from rust or staining. The background is a plain, light-colored wall.

HAM 126 1753 SFN: 3105067 SR126 over Eldora Ave.

Remove loose concrete in span 3, along median edge on east side of pier 2 over sidewalk.

05/01/2024