



Photograph 1: Rockfall at about MM 17.415 impacting the edge of roadway during the night of January 31, 2025.



Photograph 2: Debris and fallen trees impacting the shoulder at MM 17.415 on February 6, 2025.



Photograph 3: Photograph of typical rock exposure, and overhanging debris/trees from upper portion from slope within “The Narrows” taken in 2022.



Photograph 4: Debris closure onto road prompting temporary road closure in March 2019.



Photograph 5: Historical photograph of debris/rock slide from February 2019 within “The Narrows.”



Photograph 6: Historical photograph from January 2019 within vicinity of rockslide.



Photograph 7: Historical photograph from rockfall accumulation in the ditch near to MM 17.44.



Photograph 8: Areas where debris/rock was removed from ditches at about MM 17.43 in May 2025. Note, the County removed debris fall is ditches over nine days during the month of May in the following approximate MMs: 17.43, 17.9, 18.1, 18.5, and 19.03.