

Rock Slope Site BMP (State Maintained - Active): RS00003086

NLFID	SLAWSR00007**C
CRS	LAW-7-18.369
ODOT District	09
County	LAWRENCE
County CD	LAW
Route Type	State Route
Route Number	00007
Route Suffix	
CTL Begin Number	18.369
CTL End Number	18.379
STL Begin Number	18.369
STL End Number	18.379
Latitude DD Begin	38.5713132
Longitude DD Begin	-82.2954805
Latitude DD End	38.5714683
Longitude DD End	-82.2954949
PERP Date	12/30/2025
Status	Active
PID	
Let Plans URL	
Maintenance Responsibility	State
Rock Slope Site ID	RS00003086
Legacy GlobalID	RF006425
Road Functional Class	Other Principal Arterial Roads
Federal Aid Eligible	No
Road Width	24
Outside Shoulder Width	2
Inside Shoulder Width	0
Median Width	0
Lane Number Per Direction	1
Surface Type Left	Dense Graded Asphaltic Concrete
Surface Type Right	Dense Graded Asphaltic Concrete
Base Type Left	Aggregate Base 304 or Traffic Compacted
Base Type Right	Bituminous Concrete Mix or Penetration Macadam
Shoulder Type	Bituminous Concrete (AC)
Median Type	
Speed Limit	55
DSD - Decision Sight Distance (ft)	865
AADT Total Number	2976
Cardinal Direction	Yes

Driving Direction	North
Relative to Roadway	Mainline
Horizontal Position	Right
Vertical Position	Below
Slope Configuration	Multiple-angle
Slope Orientation	12
Geological System	
Geological Series	
Geological Group	
Geological System Comments	
Aggregate Thickness of Competent Beds	0.000
Aggregate Thickness of Incompetent Beds	0.000
Ratio Comp/Incomp Number of Beddings	0.000
Ratio Comp/Incomp Thickness of Beddings	0.000
Presence of Bedding	
Presence of Joint	No
Joint Pattern	
Catchment Shape	
Catchment Foreslope Angle	
Catchment Slope Face Angle	
GB-3 Guideline Width	
Associated Site Screening	RS00003086E ,RS00003086E ,RS00003086E ,RS00003086E ,
Associated Site Screening Comments	
Info Source	Field Visit
Rock Slope Comments	
Photo Link to Falcon	More info
Annual Maintenance Frequency	0
Latest Emergency Determination	No
Latest Emergency Declaration Number	
Latest Emergency Declaration Date	
Latest Tier	Tier 1
Latest Detailed Rating Score	0
Inspection Due	8
created_user	COLLECTOR@P31_AG
created_date	10/30/2020
last_edited_user	ablume
last_edited_date	2/11/2025
sys_updated_date	7/7/2026