

Rock Slope Bedding Inventory (Active, State Maintained): BED0083368

Bedding ID	BED0083368
Legacy Bedding ID	
Bedding Type	Competent
Bedding Lithology	Sandstone
Position Order	2
JRC (Joint Roughness Coefficient)	10
Bedding	Very Thick Bedded
Unit Thickness (ft)	10.00
SDI Sampling ID2 %	
Length from BMP of SDI Sample (ft)	
Height from BMP of SDI Sample (ft)	
SDI Elevation (ft)	
Bedding Inventory Comments	Crossbedding observed.
created_user	ablume
created_date	2/3/2025 5:22 PM
last_edited_user	ablume
last_edited_date	2/3/2025 5:26 PM
sys_updated_date	2/3/2025 8:10 PM

Rock Slope Bedding Inventory (Active, State Maintained): BED0083363

Bedding ID	BED0083363
Legacy Bedding ID	
Bedding Type	Competent
Bedding Lithology	Sandstone
Position Order	1
JRC (Joint Roughness Coefficient)	10
Bedding	Thick Bedded
Unit Thickness (ft)	9.00
SDI Sampling ID2 %	
Length from BMP of SDI Sample (ft)	
Height from BMP of SDI Sample (ft)	
SDI Elevation (ft)	
Bedding Inventory Comments	
created_user	ablume
created_date	2/3/2025 5:23 PM
last_edited_user	ablume
last_edited_date	2/3/2025 5:23 PM
sys_updated_date	2/3/2025 8:10 PM

Rock Slope Bedding Inventory (Active, State Maintained): BED0083362

Bedding ID	BED0083362
Legacy Bedding ID	

Bedding Type	Competent
Bedding Lithology	Sandstone
Position Order	3
JRC (Joint Roughness Coefficient)	10
Bedding	Medium Bedded
Unit Thickness (ft)	6.00
SDI Sampling ID2 %	
Length from BMP of SDI Sample (ft)	
Height from BMP of SDI Sample (ft)	
SDI Elevation (ft)	
Bedding Inventory Comments	
created_user	ablume
created_date	2/3/2025 5:21 PM
last_edited_user	ablume
last_edited_date	2/3/2025 5:21 PM
sys_updated_date	2/3/2025 8:10 PM

Rock Slope Bedding Inventory (Active, State Maintained): BED0083364

Bedding ID	BED0083364
Legacy Bedding ID	
Bedding Type	
Bedding Lithology	
Position Order	4
JRC (Joint Roughness Coefficient)	
Bedding	
Unit Thickness (ft)	140.00
SDI Sampling ID2 %	
Length from BMP of SDI Sample (ft)	
Height from BMP of SDI Sample (ft)	
SDI Elevation (ft)	
Bedding Inventory Comments	Backslope not able to be inspected. From the roadway it appears to be a mix of sandstone and natural. Bedding thicknesses are unknown.
created_user	ablume
created_date	2/3/2025 5:25 PM
last_edited_user	ablume
last_edited_date	2/3/2025 5:25 PM
sys_updated_date	2/3/2025 8:10 PM