

Rock Slope Site BMP (State Maintained - Active): RS00004384

NLFID	SLAWSR00007**C
CRS	LAW-7-17.169
ODOT District	09
County	LAWRENCE
County CD	LAW
Route Type	State Route
Route Number	00007
Route Suffix	
CTL Begin Number	17.169
CTL End Number	17.328
STL Begin Number	17.169
STL End Number	17.328
Latitude DD Begin	38.5540101
Longitude DD Begin	-82.2960015
Latitude DD End	38.5562820
Longitude DD End	-82.2955420
PERP Date	12/30/2025
Status	Active
PID	
Let Plans URL	
Maintenance Responsibility	State
Rock Slope Site ID	RS00004384
Legacy GlobalID	RF003828
Road Functional Class	Other Principal Arterial Roads
Federal Aid Eligible	No
Road Width	24
Outside Shoulder Width	2
Inside Shoulder Width	0
Median Width	0
Lane Number Per Direction	1
Surface Type Left	Dense Graded Asphaltic Concrete
Surface Type Right	Dense Graded Asphaltic Concrete
Base Type Left	Aggregate Base 304 or Traffic Compacted
Base Type Right	Bituminous Concrete Mix or Penetration Macadam
Shoulder Type	Bituminous Concrete (AC)
Median Type	
Speed Limit	55
DSD - Decision Sight Distance (ft)	865
AADT Total Number	2976
Cardinal Direction	No

Driving Direction	South
Relative to Roadway	Mainline
Horizontal Position	Right
Vertical Position	Above
Slope Configuration	Multiple-angle
Slope Orientation	190
Geological System	Pennsylvanian
Geological Series	N/A
Geological Group	Monongahela
Geological System Comments	
Aggregate Thickness of Competent Beds	0.000
Aggregate Thickness of Incompetent Beds	0.000
Ratio Comp/Incomp Number of Beddings	2.000
Ratio Comp/Incomp Thickness of Beddings	0.000
Presence of Bedding	Yes
Presence of Joint	Yes
Joint Pattern	Disc Jointing Adverse Orientation
Catchment Shape	Triangular
Catchment Foreslope Angle	33
Catchment Slope Face Angle	85
GB-3 Guideline Width	10
Associated Site Screening	LS00005925E, LS00005925E, RS00002580E, RS00002580E, RS00002580E, RS00002580E, RS00002580E,...
Associated Site Screening Comments	
Info Source	Field visit
Rock Slope Comments	Due to cutslope height and catchment foreslope angle the the GB-3 guideline width chart indicates a width of 10 feet.
Photo Link to Falcon	More info
Annual Maintenance Frequency	0
Latest Emergency Determination	No
Latest Emergency Declaration Number	
Latest Emergency Declaration Date	
Latest Tier	Tier 2
Latest Detailed Rating Score	218
Inspection Due	3
created_user	COLLECTOR@P31_AG
created_date	10/30/2020
last_edited_user	ablume

last_edited_date	2/4/2025
sys_updated_date	7/7/2026