

**Rock Slope Site BMP (State Maintained - Active): RS00005880**

|                                    |                                                |
|------------------------------------|------------------------------------------------|
| NLFID                              | SLAWSR00007**C                                 |
| CRS                                | LAW-7-17.879                                   |
| ODOT District                      | 09                                             |
| County                             | LAWRENCE                                       |
| County CD                          | LAW                                            |
| Route Type                         | State Route                                    |
| Route Number                       | 00007                                          |
| Route Suffix                       |                                                |
| CTL Begin Number                   | 17.879                                         |
| CTL End Number                     | 17.927                                         |
| STL Begin Number                   | 17.879                                         |
| STL End Number                     | 17.927                                         |
| Latitude DD Begin                  | 38.5642233                                     |
| Longitude DD Begin                 | -82.2952238                                    |
| Latitude DD End                    | 38.5649220                                     |
| Longitude DD End                   | -82.2952230                                    |
| PERP Date                          | 12/30/2025                                     |
| Status                             | Active                                         |
| PID                                |                                                |
| Let Plans URL                      |                                                |
| Maintenance Responsibility         | State                                          |
| Rock Slope Site ID                 | RS00005880                                     |
| Legacy GlobalID                    |                                                |
| Road Functional Class              | Other Principal Arterial Roads                 |
| Federal Aid Eligible               | No                                             |
| Road Width                         | 24                                             |
| Outside Shoulder Width             | 2                                              |
| Inside Shoulder Width              | 0                                              |
| Median Width                       | 0                                              |
| Lane Number Per Direction          | 1                                              |
| Surface Type Left                  | Dense Graded Asphaltic Concrete                |
| Surface Type Right                 | Dense Graded Asphaltic Concrete                |
| Base Type Left                     | Aggregate Base 304 or Traffic Compacted        |
| Base Type Right                    | Bituminous Concrete Mix or Penetration Macadam |
| Shoulder Type                      | Bituminous Concrete (AC)                       |
| Median Type                        |                                                |
| Speed Limit                        | 55                                             |
| DSD - Decision Sight Distance (ft) | 865                                            |
| AADT Total Number                  | 2976                                           |
| Cardinal Direction                 | Yes                                            |

|                                         |                           |
|-----------------------------------------|---------------------------|
| Driving Direction                       | North                     |
| Relative to Roadway                     | Mainline                  |
| Horizontal Position                     | Right                     |
| Vertical Position                       | Below                     |
| Slope Configuration                     | Multiple-angle            |
| Slope Orientation                       | 349                       |
| Geological System                       | Pennsylvanian             |
| Geological Series                       |                           |
| Geological Group                        | Conemaugh                 |
| Geological System Comments              |                           |
| Aggregate Thickness of Competent Beds   | 0.000                     |
| Aggregate Thickness of Incompetent Beds | 0.000                     |
| Ratio Comp/Incomp Number of Beddings    | 0.000                     |
| Ratio Comp/Incomp Thickness of Beddings | 0.000                     |
| Presence of Bedding                     |                           |
| Presence of Joint                       |                           |
| Joint Pattern                           |                           |
| Catchment Shape                         |                           |
| Catchment Foreslope Angle               |                           |
| Catchment Slope Face Angle              |                           |
| GB-3 Guideline Width                    |                           |
| Associated Site Screening               | RS00005879E, RS00005879E, |
| Associated Site Screening Comments      |                           |
| Info Source                             | Field visit               |
| Rock Slope Comments                     |                           |
| Photo Link to Falcon                    |                           |
| Annual Maintenance Frequency            | 0                         |
| Latest Emergency Determination          | No                        |
| Latest Emergency Declaration Number     |                           |
| Latest Emergency Declaration Date       |                           |
| Latest Tier                             | Tier 1                    |
| Latest Detailed Rating Score            | 0                         |
| Inspection Due                          | 8                         |
| created_user                            | ashelter                  |
| created_date                            | 2/21/2022                 |
| last_edited_user                        | ablume                    |
| last_edited_date                        | 2/12/2025                 |
| sys_updated_date                        | 7/7/2026                  |