

Inspect
Inspect

Ohio Bridges Summary Report

2: District 11 WARREN TWP (JEF county)
11

21: Major Maint A/B 01 - State Highway Agency /01 7: Facility On 00007
225 Routine Main A/B 01 - State Highway Agency /01 6: Feature Ints Shannon's Run
221 Inspection A/B 01 - State Highway Agency /01 9: Location 1.33 mi N of JCT SR 150
220: Inv. Location District 11 Lat, Lon 40.2064 , -80.671

5A: Inventory Route 1 00007

7-9-2025

Condition		Structure Type	
58: Deck	N - Not Applicable	43: Bridge Type	3 - Steel
58.01 Wearing Surface	N - Not Applicable	19 - Culvert (includes frame culverts)	
58.02 Joint	N - Not Applicable	N - Not Applicable	
59: Superstructure	N - Not Applicable	45: Spans Main / Approach	1 / 0
59.01 Paint & PCS	N - Not Applicable	107: Deck Type	N - Not Applicable
60: Substructure	N - Not Applicable	408: Composite Deck	U - Unknown
61: Channel	4	414A Joint Type 1	N - None
61.01 Scour	4 - Poor or Advanced Scour (Spread: no undermining, Deep: Piles may be visible)	414B: Joint Type 2	N - None
62: Culverts	4 - Large spalls, heavy scaling, wide cracks	108A: Wearing Surface	N - NA
67.01 GA	4		N - Not Applicable
Appraisal			
Sufficiency Rating	48.8	SD/FO	1 - SD
36: Rail, Tr, Gd, Term Std	N	N	1 1
72: Approach Alignment	6 - Equal to present minimum criteria		
113: Scour Critical	6 - Not yet evaluated for scour		
71: Waterway Adequacy	4 - Occasional Flooding - Significant		
		422: WS Date	
		423: WS Thick (in)	0.0
		482: Protective Coating	N - None or Not Applicable
		483: PCS Date	
		453: Bearing Type 1	N - None
		455: Bearing Type 2	N - None
		528: Foundn: Abut Fwd	N - None (Such as most Culverts)





























