

CRS:	HAS-Rabbit Rd Rehabilitation	PID:	122492	Date:	11/26/25
------	------------------------------	------	--------	-------	----------

## ENVIRONMENTAL SOS

Task	Task#	Required	Preparer	Comments
CE Level: <b>C1</b>	3.5.A	<b>X</b>	<b>D11</b>	
Purpose and Need Statement	1.3.G			
Cultural Resource SRF	2.2.B			<b>Appendix A</b>
Phase I Cultural Archaeological	3.1.A			
Phase I Cultural History Arch	2.2.I			
Phase II Cultural History Arch	3.1.B			
Section 4(f) Determination/Coord	2.2.F & 3.1.C			
Recreational Boating Review Form	NA			
Ecological Survey Level: <b>Exempt</b>	2.2.C	<b>X</b>	<b>D11</b>	
Mussel Survey	3.1.Q			
Section 9/Section 10 Coordination	3.1.M.C			
Permit Determination Request	3.1.M.A			
Section 404 PCN	3.1.M.B			
404 Individual Permit	3.1.M.D			
OEPA Director's Authorization App	3.1.M.H			
401 Water Quality Application	3.1.M.C			
Flood Plain Coordination	2.3.H.A			
Scenic River Coordination	NA			
Public Involvement	2.2.A & 2.6.A			
FCIR Form	3.1.E			
RMR Screening	2.2.D	<b>X</b>	<b>D11</b>	
RMR Assessment	3.1.D			
RMR Investigation	3.1.O			
Noise Analysis	2.2.G & 2.2.H			
Air Quality Analyses	3.1.P			
Asbestos Inspection	NA			

CRS:	HAS-Rabbit Rd Rehabilitation	PID:	122492	Date:	11/26/25
------	------------------------------	------	--------	-------	----------

ENVIRONMENTAL SOS

<b>Additional Comments:</b>
Wetlands and multiple streams (UNTs) present but all will be avoided. Multiple culverts have streams formed at outlet ends which are located off the ROW. If such culverts are replaced, all work will remain within the ROW and out of the stream(s).

