

**IN-DEPTH PHYSICAL CONDITION REPORT  
Of The  
LORAIN-CARNEGIE BRIDGE  
S.R. 10**

**BRIDGE NO. CUY-10-1613  
SFN: 1801503**

**CLEVELAND, OHIO**

**Prepared by:**

Anthony D. Koloze, EI \_\_\_\_\_

**Reviewed by:**

Wesley R. Weir, PE \_\_\_\_\_  
OH PE#: 69991

Inspected on:

September 21 through December 17, 2010

Inspected by:  
Wesley R. Weir, PE  
Carolyn Guion, PE  
Anthony Koloze, EI  
Donald Cartwright, EI  
Nicholas Fisco, EI  
Jeffrey Hill, EI  
Kevin Williams

Prepared for:

**OHIO DEPARTMENT OF TRANSPORTATION  
DISTRICT 12**

Report Submitted March 23, 2011

TranSystems  
55 Public Square, Suite 1900  
Cleveland, OH 44113

## TABLE OF CONTENTS

Bridge Description .....	1
Inspection Procedure.....	2
Inspection Team .....	2
Condition Rating .....	3
Deck Summary .....	4
Superstructure Summary.....	7
Substructure Summary.....	19
Conclusions and Recommendations .....	24
Appendix A: Plan and Profile of Bridge	
Appendix B: Top of Deck Deficiencies	
Appendix C: Utility Deck Deficiencies	
Appendix D: Main Truss Spans Top and Bottom Chord Deficiencies	
Appendix E: KCI Associates of Ohio Underwater Inspection Report	
Appendix F: BR-86 Bridge Inspection Report	

# APPENDIX A

## Plan and Profile of Bridge

# APPENDIX B

## Top of Deck Deficiencies

# APPENDIX D

## Main Truss Spans Top and Bottom Chord Deficiencies

# APPENDIX C

## Utility Deck Deficiencies

# APPENDIX E

KCI Associates of Ohio  
Underwater Inspection Report

# APPENDIX F

## BR-86 Bridge Inspection Report