

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INVENTORY REPORT

CR-86 12-03

287000171

CULVERT FILE NUMBER

1. Entry Class

A

LOCATION AND ROUTE INFORMATION

2. District	12	3. County	GEA
4. Route	SR 700	5. Straight Line Mileage	1.719
6. Latitude	41.37216	7. Longitude	-81.14314
8. Road ID		9. Maintenance Responsibility	S
10. Feature Intersection			

CULVERT

11. Year Built	9999	12. Number of Cells	1
13. Shape	8	14. Material	15
15. Span (in.)	36	16. Rise (in.)	36
17. Length (ft.)	35	18. Gage (no.) / Wall Thickness (in.)	
19. Gage (no.) / Wall Thickness (in.)		20. Type of Protection	1
21. Slope of Pipe (%)	1.14	22. Skew (degrees)	
23. Inlet End Treatment	1	24. Outlet End Treatment	1
25. Maximum Height of Cover (ft.)	2	26. Modification Type	
27. Year Modified		28. Modification Material	
29. Modification Size (in.)			

EXTENSION - INLET

30. Year Extended		31. Shape	
32. Material		33. Span (in.)	
34. Rise (in.)		35. Gage (no.) / Wall Thickness (in.)	
36. Extension Length			

EXTENSION - OUTLET

37. Year Extended		38. Shape	
39. Material		40. Span (in.)	
41. Rise (in.)		42. Gage (no.) / Wall Thickness (in.)	
43. Extension Length (ft.)			

HYDROLOGY / HYDRAULICS

44. Drainage Area (acres)		45. Design Discharge (c.f.s.)	
46. Abrasive Conditions	N	47. pH	7.6
48. Channel Protection (Inlet)	G	49. Channel Protection (Outlet)	G

COMMENTS:

SEE GEA-700-0.00 SHEETS 6/8 AND 8/8. Inspect Every-Five Years

INVENTORIED BY: LM DATE: 2/10/2016