

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INVENTORY REPORT

CR-87 12-03

436080314

CULVERT FILE NUMBER

1. Entry Class

A

LOCATION AND ROUTE INFORMATION

2. District	12	3. County	LAK
4. Route	SR 608	5. Straight Line Mileage	3.133
6. Latitude	41.67288	7. Longitude	-81.21628
8. Road ID		9. Maintenance Responsibility	S
10. Feature Intersection	ALEXANDER RD.		

CULVERT

11. Year Built		12. Number of Cells	1
13. Shape	1	14. Material	1
15. Span (in.)	36	16. Rise (in.)	36
17. Length (ft.)	48	18. Gage (no.) / Wall Thickness (in.)	
19. Gage (no.) / Wall Thickness (in.)		20. Type of Protection	1
21. Slope of Pipe (%)		22. Skew (degrees)	
23. Inlet End Treatment	NN	24. Outlet End Treatment	8
25. Maximum Height of Cover (ft.)		26. Modification Type	
27. Year Modified		28. Modification Material	
29. Modification Size (in.)			

EXTENSION - INLET

30. Year Extended		31. Shape	
32. Material		33. Span (in.)	
34. Rise (in.)		35. Gage (no.) / Wall Thickness (in.)	
36. Extension Length			

EXTENSION - OUTLET

37. Year Extended		38. Shape	
39. Material		40. Span (in.)	
41. Rise (in.)		42. Gage (no.) / Wall Thickness (in.)	
43. Extension Length (ft.)			

HYDROLOGY / HYDRAULICS

44. Drainage Area (acres)		45. Design Discharge (c.f.s.)	
46. Abrasive Conditions	N	47. pH	
48. Channel Protection (Inlet)		49. Channel Protection (Outlet)	

COMMENTS:

Inlet is plastic, middle of culvert looks like a concrete box culvert. Outlet looks like concrete pipe
 Inlet is plastic, middle of culvert looks like a concrete box culvert. Outlet looks like concrete pipe

 INVENTORIED BY: WS DATE: 5/20/2005