

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INVENTORY REPORT

CR-86 12-03

182520205

CULVERT FILE NUMBER

1. Entry Class

B

LOCATION AND ROUTE INFORMATION

2. District	12	3. County	CUY
4. Route	SR 252	5. Straight Line Mileage	2.456
6. Latitude	41.385278	7. Longitude	-81.902778
8. Road ID		9. Maintenance Responsibility	S
10. Feature Intersection			

CULVERT

11. Year Built		12. Number of Cells	1
13. Shape	4	14. Material	2
15. Span (in.)	84	16. Rise (in.)	84
17. Length (ft.)	40	18. Gage (no.) / Wall Thickness (in.)	
19. Gage (no.) / Wall Thickness (in.)		20. Type of Protection	1
21. Slope of Pipe (%)		22. Skew (degrees)	
23. Inlet End Treatment	10	24. Outlet End Treatment	10
25. Maximum Height of Cover (ft.)		26. Modification Type	
27. Year Modified		28. Modification Material	
29. Modification Size (in.)			

EXTENSION - INLET

30. Year Extended		31. Shape	
32. Material		33. Span (in.)	
34. Rise (in.)		35. Gage (no.) / Wall Thickness (in.)	
36. Extension Length			

EXTENSION - OUTLET

37. Year Extended		38. Shape	
39. Material		40. Span (in.)	
41. Rise (in.)		42. Gage (no.) / Wall Thickness (in.)	
43. Extension Length (ft.)			

HYDROLOGY / HYDRAULICS

44. Drainage Area (acres)		45. Design Discharge (c.f.s.)	
46. Abrasive Conditions	N	47. pH	8.4
48. Channel Protection (Inlet)		49. Channel Protection (Outlet)	

COMMENTS:

SLOPE WASHOUTSLOPE WASHOUT

INVENTORIED BY: _____ GN _____ DATE: 7/3/2013