

OHIO DEPARTMENT OF TRANSPORTATION

BRIDGE INSPECTION REPORT

1	8	0	1	5	0	3	CUY	00010	1613	YEAR BUILT	1932	
STRUCTURE FILE NUMBER							CO	ROUTE	UNIT			
DIST	12	BRIDGE TYPE	343		TYPE OF SERVICE	57	CUY RIVER VALLEY & FI RR					

DECK

1. Floor	3	2. Wearing Surface	1
3. Curbs, Sidewalks & Walkways	1	4. Median	
5. Railing	1	6. Drainage	1
7. Expansion Joints	2	8. SUMMARY	5

SUPERSTRUCTURE

9. Alignment of Members	1	10. Beams/Girders/Slab	1
11. Diaphragms or Cross frames	1	12. Joists/Stringers	2
13. Floorbeams	2	14. Floorbeam Connections	1
15. Verticals	2	16. Diagonals	2
17. End posts		18. Upper Chord	1
19. Lower Chord	3	20. Gusset Plates	3
21. Lateral Bracing	1	22. Sway Bracing	1
23. Portals		24. Bearing Devices	2
25. Arch		26. Arch Columns or Hangers	
27. Spandrel Walls		28. Protective Coating System (PCS)	7
29. Pins/Hangers/Hinges	2	30. Fatigue Prone Detail (E & E')	1
31. Live Load Response (E or S)	S	32. SUMMARY	4

SUBSTRUCTURE

33. Abutments	1	34. Abutment Seats	1
35. Piers	2	36. Pier Seats	1
37. Backwalls	1	38. Wingwalls	1
39. Fenders and Dolphins	4	40. Scour (Insp Type - 1, 2, 3)	3 2
41. Slope Protection		42. SUMMARY	6

CULVERT

43. General		44. Alignment	
45. Shape		46. Seams	
47. Headwall or Endwalls		48. Scour (Insp Type - 1,2,3)	
49. Abutments		50. SUMMARY	

CHANNEL

51. Alignment	2	52. Protection	2
53. Hydraulic Opening	1	54. SUMMARY	6

APPROACHES


55. Pavement	1	56. Approach Slabs	1
57. Guardrail	1	58. Relief Joint	
59. Embankment	1	60. SUMMARY	8

GENERAL

61. Navigation Lights	1	62. Warning Signs	
63. Sign Supports		64. Utilities	3
65. Vertical Clearance (1, 2-change, N)	N	66. General Appraisal & Operational Status	4 A

67. Inspected By, First & Last Name

68. Reviewed By, First & Last Name

  
Anthony D. Koloze

PE Number

  
Wesley R. Weir, P.E.  
P.E.# 69991  
PE Number

Date 12/7/2011

1	1	1	1	0	0	0	N
---	---	---	---	---	---	---	---

Date 12/7/2011

69. Survey (1, 0, N)