



National Engineering &
Architectural Services, INC. (NEAS)
2800 Corporate Exchange Dr.
Suite 240
Columbus, Ohio 43231
Office: (614) 714-0299
Fax: (614) 714-0251

LEVEL A TEST HOLE CERTIFICATION FORM

PROJECT NAME: DEL-42-12.63, CULVERT REPLACEMENT , PID#: 126936
NEAS PROJECT #: 26-0045
PROJECT LOCATION (CTY.,CITY,ST.): DEL, BROWN TWP., U.S. 42 N.
FOREMAN/TRUCK: N. MILLER
DATE OF EXCAVATION: 08-18-26
WEATHER CONDITIONS: 69° SUNNY

TEST HOLE #: 1
UTILITY TO BE LOCATED:
FIBER OPTIC (FOUND)

UTILITY OWNER - CONSOLIDATED COOPERATIVE

CONTROL POINT: SSV2
NORTHING: 521098.390
EASTING: 204057.922
ELEVATION: 944.666

HORIZONTAL DATUM: NAD83 (2011)
COORDINATE SYSTEM: DELAWARE COUNTY LDP
VERTICAL DATUM: NAVD88
UNITS: US Survey Foot
CSF: N/A

SIZE OF UTILITY: (2) 2"
MATERIAL OF FOUND UTILITY: SPP
THE UTILITY WAS IN GOOD CONDITION
THERE WERE NOT ADDITIONAL UTILITIES IN THE TEST HOLE
SURVEYED ELEVATION TOP OF UTILITY: 935.452
SURVEYED ELEVATION BOTTOM OF HOLE: N/A
SURVEYED NORTHING TOP OF UTILITY: 521290.870
SURVEYED EASTING TOP OF UTILITY: 204065.744
SURVEYED STATION: XXXX+XX.XX, OFFSET: XX.XX' XX
DEPTH OF TOP OF UTILITY FROM SURFACE: 8.75'
DIRECTION OF UTILITY LINE: SW / NE
PHOTO IMAGE NUMBERS: TH1A, TH1B

TEST HOLE LOCATION (PAV., BERM, ETC): SHOULDER GRASS
EXISTING SURFACE GRADE ELEVATION: 944.200
PAVING CONDITION PRIOR TO WORK: N/A
PAVING THICKNESS AND TYPE: N/A
SOIL TYPE: DIRT & CLAY FIELD CONDITIONS: WET
COLOR OF RIBBON INSTALLED IN TEST HOLE: N/A

FIELD/UTILITY REMARKS: FOUND (2) ORANGE 2" SPP @ FLAGS MBO AND CONFIRMED BY NEAS.



UTILITY LEGEND

GAS	— G —	⊕ TEST HOLE	⊕ ELEC. P.B.
WATER	— W —	⊕ FIRE HYDRANT	⊕ POWER POLE
TELEPHONE	— T —	⊕ WATER VALVE	⊕ POWER/LIGHT
ELECTRIC	— E —	+G GAS MARKER	⊕ LIGHT POLE
SANITARY SEWER	— SAN —	⊕ GAS VALVE	⊕ SAN M.H.
STORM SEWER	— S —	○ F.O. MARKER	⊕ TRAFFIC P.B.
FIBER OPTIC	— FO —	⊕ UNKNOWN P.B.	X GROUND SHOT
CABLE TV	— CTV —		
TRAFFIC	— TR —		

I, Charles W. Price, JR. do hereby certify that the positioning of the utility facilities provided utilizing (Utility Quality Level A, Utility Quality Level B, or Utility Quality Level C as applicable) was performed in accordance with ODOT'S Subsurface Utility Engineering Specifications.

Charles W. Price, JR., P.S. S-7825

DATE 08-20-26

