

STATE OF OHIO  
DEPARTMENT OF HIGHWAYS  
TESTING LABORATORY

## LOG OF BORING

CO., RT. NO., SEC. FRA-40-12.82 BRIDGE NO. FRA-40-1334  
FORWARD ABUTMENT SOUTH INNERBELT UNDER FOURTH STREET  
 LOCATION: T.H. 12 B STA. 53+47 OFFSET 33' LT FED. NO. \_\_\_\_\_

ELEV.	DEPTH	NO. BLOWS	SAMPLE NO.	DESCRIPTION
751.2	0			Sidewalk
	2			
	4			
746.2	6			Fill Material-Brown Clay W/Gravel and Fragments of Stone and Brick
	8			
741.2	10			
	12	15/22	21450	Brownish-Gray Gravelly Sandy Silt W/ Stone Fragments and Brick
738.7	14	18/23	21451	Brownish-Gray Sandy Silt W/Stone Fragments
736.2	16	15/25	21452	Brownish-Gray Sandy Silt W/Stone Fragments
733.7	18	33/70	21453	Gray Silty Sandy Gravel
731.2	20	36/*	21454	Gray Gravel
728.7	22			
	24	25/50	21455	Gray Gravelly Sand
726.2	26	17/50	21456	Gray Gravelly Sand
723.7	28	23/42	21457	Gray Sandy Gravel
721.2	30			
	32	17/56	21458	Gray Sandy Gravel
	34			
716.2	36	27/53	21459	Gray Sandy Gravel