

Map Check Report

Report Created: Tuesday, June 10, 2025
Time: 2:15:04 PM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0328760\114960_BR001_96RW.dgn

Last Revised: 6/10/2025 14:14:59

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 10SH1

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S88.249°W	270.000		
HPI	(HPI)	-8.251	-269.874	0.000
	N27.974°E	46.060		
HPI	(HPI)	32.428	-248.268	0.000
	S87.610°E	207.700		
HPI	(HPI)	23.765	-40.749	0.000
	S59.746°E	47.170		
POT	(POT)	-0.001	-0.004	0.000

Northing Error: -0.001 ft
Easting Error: -0.004 ft
Closing Direction: N75.110°E
Closing Distance: 0.004 ft
Closed Area: 7689.179 sq ft 0.177 ac
Perimeter: 570.930 ft
Precision: 152047 : 1